

# START

0016300

AMENDMENTS FOR THE NRDL  
MANIFEST RECORDS FOR YEAR  
1985

BEST AVAILABLE COPY



5-1-6

1. These pages consist of the NRDWL internal shipping documents that were stored at the NRDWL caretaker trailer and the Seattle records center. The trailer is located at the Solid Waste Landfill, south and adjacent of the NRDWL.
2. These pages are duplicates of those stored at the NRDWL operations facility.
3. Insert these pages at the back of the binder of the initial submittal "Manifest Records Nonradioactive Dangerous Waste Landfill for year 1985", on February 14, 1991.

<b>Rockwell Hanford Operations</b>		<b> DANGEROUS WASTE TREATMENT, STORAGE AND DISPOSAL RECORD </b>					
<b> STORAGE/DISPOSAL ACTIVITY </b>				<b> ORIGINATOR </b>			
Onsite Disposal (DB1): <input type="checkbox"/> Oxidizer Trench <input checked="" type="checkbox"/> Corrosive Trench <input type="checkbox"/> Asbestos Trench				End Function: <u>UN</u>		Manifest Number: <u>UNC - 12-39B</u>	
Non-PCB Onsite Storage (SO1), Offsite TSD. <input type="checkbox"/> PCB Onsite Storage/Offsite Disposal: <input type="checkbox"/>				Company: <u>UNC</u>		Building/Area: <u>105N/100N</u>	
Contact Person: <u>K H Smith</u>				Address/Phone: <u>105N/100N</u>			
<b> PHYSICAL DESCRIPTION </b>							
Item No.	Description Of Waste	DOT Hazard Class	W DOE DW Number(s)	Weight (KG)	Volume Of Waste and Container (FT <sup>3</sup> )	Generating Facility Bldg./Area	
1	Non-regulated, empty drums (31)	None	None	986	226	105N/100N	
2							
3							
4							
5							
6							
7							
8							
9							
10							
For additional items, continue on the back of this form.				Total Weight (Front & Back) <u>986</u> KG		Total Volume (Front & Back) <u>226</u> FT <sup>3</sup>	
<b> TREATMENT, STORAGE, AND DISPOSAL INFORMATION (To be completed by Rockwell) </b>							
<b> ONSITE DISPOSAL: </b>		Disposal Date:		Signature: Disposer			
Trench Location:		Beginning Coordinates: N		W			
		Ending Coordinates: N		W			
<b> NON PCB OFFSITE DISPOSAL </b>		Storage Time:		Arrival Date:			
		Offsite TSD		Date Shipped:			
				Facility Name:			
				Facility Address:			
				TSD Process:    Landfill (DB1): <input type="checkbox"/> Disposal Date Treatment (TO ____): <input type="checkbox"/> Treatment Date Specify Treatment Activity  Other ( ____ ): <input type="checkbox"/> Specify Activity			
<b> PCB OFFSITE DISPOSALS </b>		Storage Time:		Beginning Date:			
		Offsite Disposal:		Date Shipped:			
				Facility Name:			
				Facility Address:			
<b> COMMENTS: </b>							

000279

A-6400-249 (11-84)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. WA 789 000 8967		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.					
3. Generator's Name and Mailing Address K H Smith 105-N/100 N 373-4940				UNC 12-29B		A. State Manifest Document Number							
4. Generator's Phone ( 509 ) 373-4940						B. State Generator's ID							
5. Transporter 1 Company Name Rockwell Hanford				6. US EPA ID Number WA 789 000 8967		C. State Transporter's ID							
7. Transporter 2 Company Name NA				8. US EPA ID Number NA		D. Transporter's Phone 376-1420							
9. Designated Facility Name and Site Address Chemical Trench, Central Landfill				10. US EPA ID Number WA 789 000 8967		E. State Transporter's ID							
						F. Transporter's Phone							
						G. State Facility's ID							
						H. Facility's Phone (509) 376-6748							
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers		13. Total Quantity		14. Unit Wt/Vol		15. Waste No.	
a. Non-regulated Empty Drums						31		226		FT <sup>3</sup>		None	
b.													
c.													
d.													
J. Additional Descriptions for Materials Listed Above						K. Handling Codes for Wastes Listed Above							
15. Special Handling Instructions and Additional Information													
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.													
Printed/Typed Name Richard L Southam						Signature Richard L Southam						Date 5 17 85	
17. Transporter 1 Acknowledgement of Receipt of Materials						Signature E. F. Rojas						Date 5 17 85	
18. Transporter 2 Acknowledgement of Receipt of Materials						Signature						Date	
Printed/Typed Name						Signature						Date	
19. Discrepancy Indication Space													
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.													
Printed/Typed Name D-E-Phelps						Signature D-E-Phelps						Date 5 17 85	

000280

TRANSPORTER =1

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>MA 789 000 8967</b>		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.					
3. Generator's Name and Mailing Address <b>K H Smith 105-N/100 N 373-4940</b>						A. State Manifest Document Number							
						B. State Generator's ID							
4. Generator's Phone ( 509 ) <b>373-4940</b>				6. US EPA ID Number <b>MA 789 000 8967</b>		C. State Transporter's ID							
5. Transporter 1 Company Name <b>Rockwell Hanford</b>						D. Transporter's Phone <b>376-1420</b>							
7. Transporter 2 Company Name <b>HA</b>				8. US EPA ID Number <b>MA</b>		E. State Transporter's ID							
						F. Transporter's Phone							
9. Designated Facility Name and Site Address <b>Chemical Trench, Central Landfill</b>				10. US EPA ID Number <b>MA 789 000 8967</b>		G. State Facility's ID							
						H. Facility's Phone <b>(509) 376-6743</b>							
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers		13. Total Quantity		14. Unit Wt/Vol		15. Waste No.	
						No. Type							
a. <b>Non-regulated Empty Drums</b> <b>None</b> <b>None</b>						<b>31 DM</b>		<b>226</b>		<b>FT<sup>3</sup></b>		<b>None</b>	
b.													
c.													
d.													
J. Additional Descriptions for Materials Listed Above						K. Handling Codes for Wastes Listed Above							
15. Special Handling Instructions and Additional Information													
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.													
Printed/Typed Name <b>Richard L Southam</b>						Signature <i>Richard L Southam</i>				Date <b>Month Day Year</b> <b>17 1985</b>			
17. Transporter 1 Acknowledgement of Receipt of Materials										Date			
Printed/Typed Name <b>R. L. Southam</b>						Signature <i>R. L. Southam</i>				Month Day Year <b>17 1985</b>			
18. Transporter 2 Acknowledgement of Receipt of Materials										Date			
Printed/Typed Name						Signature				Month Day Year			
19. Discrepancy Indication Space													
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.										Date			
Printed/Typed Name <b>D-E-Phelps</b>						Signature <i>D E Phelps</i>				Month Day Year <b>15 17 85</b>			

000281

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>WA 789 000 8967</b>		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.					
		3. Generator's Name and Mailing Address <b>P. J. Hamacher 271-B/200 East</b>		<b>RHO 12-25B</b>		A. State Manifest Document Number		B. State Generator's ID					
4. Generator's Phone (509) <b>373-2558</b>		5. Transporter 1 Company Name <b>Rockwell Hanford</b>		6. US EPA ID Number <b>WA 789 000 8967</b>		C. State Transporter's ID		D. Transporter's Phone <b>376-1420</b>					
7. Transporter 2 Company Name <b>NA</b>		8. US EPA ID Number <b>NA</b>		E. State Transporter's ID		F. Transporter's Phone		G. State Facility's ID					
9. Designated Facility Name and Site Address <b>Central Landfill Corrosive Trench</b>		10. US EPA ID Number <b>WA 789 000 8967</b>		H. Facility's Phone <b>(509) 376-6743</b>									
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)				12. Containers		13. Total Quantity		14. Unit Wt/Vol		15. Waste No.			
				No. Type									
				a. <input type="checkbox"/> HM <b>Waste, Non-regulated empty drums</b> <b>None</b> <b>None</b>		<b>6</b> <b>DM</b>		<b>34</b>		<b>Ft<sup>3</sup></b>		<b>z None</b>	
				b. <input type="checkbox"/>									
				c. <input type="checkbox"/>									
d. <input type="checkbox"/>													
J. Additional Descriptions for Materials Listed Above						K. Handling Codes for Wastes Listed Above							
15. Special Handling Instructions and Additional Information													
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.													
Printed/Typed Name						Signature			Date				
						<i>[Signature]</i>			Month Day Year				
17. Transporter 1 Acknowledgement of Receipt of Materials						Signature			Date				
Printed/Typed Name						<i>[Signature]</i>			Month Day Year				
<b>E. F. Kulas</b>						<b>E. F. Kulas</b>			<b>7 22 85</b>				
18. Transporter 2 Acknowledgement of Receipt of Materials						Signature			Date				
Printed/Typed Name									Month Day Year				
19. Discrepancy Indication Space													
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.													
Printed/Typed Name						Signature			Date				
<b>DE PHELIS</b>						<i>[Signature]</i>			Month Day Year				
									<b>15 17 85</b>				

000282

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. WA 789 000 8967		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.					
3. Generator's Name and Mailing Address K H Smith 105 N/100N						A. State Manifest Document Number							
4. Generator's Phone (509) 373-4940						B. State Generator's ID							
5. Transporter 1 Company Name Rockwell Hartford						C. State Transporter's ID							
6. US EPA ID Number WA 789 000 8967						D. Transporter's Phone 376-1420							
7. Transporter 2 Company Name NA						E. State Transporter's ID							
8. US EPA ID Number NA						F. Transporter's Phone							
9. Designated Facility Name and Site Address Central Landfill Chemical Trench						G. State Facility's ID							
10. US EPA ID Number WA 789 000 8967						H. Facility's Phone (509) 376-6748							
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers		13. Total Quantity		14. Unit Wt/Vol		15. Waste No.	
a. waste oil and sand (Non-regulated) None None						110 24		780		Ft <sup>3</sup>		None	
b.													
c.													
d.													
J. Additional Descriptions for Materials Listed Above 102 55-gal drums 8 30-gal drums						K. Handling Codes for Wastes Listed Above							
15. Special Handling Instructions and Additional Information													
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.													
Printed/Typed Name Richard L. Southam						Signature Richard L. Southam		Approved by L J Lust		Date 5 17 85			
17. Transporter 1 Acknowledgement of Receipt of Materials						Signature Jeffrey A. Fee		Date 5 17 85					
18. Transporter 2 Acknowledgement of Receipt of Materials						Signature		Date					
19. Discrepancy Indication Space													
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						Date							
Printed/Typed Name D E Phelps						Signature D E Phelps		Date 5 17 85					

000283

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. WA7 89 000 8967		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.					
3. Generator's Name and Mailing Address PNL c/o - Jeene Hobbs, 3762/300 Area 4. Generator's Phone ( 509 ) 376-1631						PNL-7-23 PNL-M-85-001							
5. Transporter 1 Company Name Rockwell Hanford Operations						6. US EPA ID Number WA7 89 000 8967							
7. Transporter 2 Company Name NA						8. US EPA ID Number NA							
9. Designated Facility Name and Site Address Chemical Trench - Central Landfill Hanford Project						10. US EPA ID Number WA7 89 000 8967							
A. State Manifest Document Number						B. State Generator's ID							
C. State Transporter's ID						D. Transporter's Phone 376-1420							
E. State Transporter's ID						F. Transporter's Phone							
G. State Facility's ID						H. Facility's Phone							
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers		13. Total Quantity		14. Unit Wt/Vol		15. Waste No.	
a. Waste calcium nitrate, oxidizer, UN1454						3		17H 55		675		P 0001	
b. Waste sodium nitrate, oxidizer, UN1493						1		17H		50		P 0001	
c.													
d.													
J. Additional Descriptions for Materials Listed Above Item a is packed in drums numbered PNL-85-01,02,003. Item b is packed in drum number PNL-85-04.						K. Handling Codes for Wastes Listed Above							
15. Special Handling Instructions and Additional Information The chemicals are currently stored at 332. This document corresponds to disposal request PNL-84-006 (RHO 84-7-23).													
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.													
Printed/Typed Name Jeene Hobbs						Signature		Date 5/14/85					
17. Transporter 1 Acknowledgement of Receipt of Materials						Signature		Date					
Printed/Typed Name						Signature		Date					
18. Transporter 2 Acknowledgement of Receipt of Materials						Signature		Date					
Printed/Typed Name LANCE S HAVIS						Signature		Date 5/14/85					
19. Discrepancy Indication Space													
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.													
Printed/Typed Name P.L. - LHS						Signature		Date 5/14/85					

000281

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>WA7 89 000 8967</b>		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.					
3. Generator's Name and Mailing Address <b>PNL c/o - Jeene Hobbs, 3762/300 Area</b>						A. State Manifest Document Number <b>PNL-723</b>							
						B. State Generator's ID <b>PNL-M-85-001</b>							
4. Generator's Phone ( 509 ) 376-1631						C. State Transporter's ID							
5. Transporter 1 Company Name <b>Rockwell Hanford Operations</b>						D. Transporter's Phone <b>376-1420</b>							
6. US EPA ID Number <b>WA7 89 000 8967</b>						E. State Transporter's ID							
7. Transporter 2 Company Name <b>NA</b>						F. Transporter's Phone							
8. US EPA ID Number <b>NA</b>						G. State Facility's ID							
9. Designated Facility Name and Site Address <b>Chemical Trench - Central Landfill Hanford Project</b>						H. Facility's Phone <b>376-16748</b>							
10. US EPA ID Number <b>WA7 89 000 8967</b>													
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers		13. Total Quantity		14. Unit Wt/Vol		15. Waste No.	
						No.	Type						
a. <b>Waste calcium nitrate, oxidizer, UN1454</b>						<b>3</b>	<b>17H 55</b>	<b>675</b>	<b>P</b>	<b>D001</b>			
b. <b>Waste sodium nitrate, oxidizer, UN1498</b>						<b>1</b>	<b>17H</b>	<b>50</b>	<b>P</b>	<b>D001</b>			
c.													
d.													
J. Additional Descriptions for Materials Listed Above Item a is packed in drums numbered PNL-85-01,02,&03. Item b is packed in drum number PNL-85-04.								K. Handling Codes for Wastes Listed Above					
15. Special Handling Instructions and Additional Information The chemicals are currently stored at 332. This document corresponds to disposal request PNL-84-006 (RHO 84-7-23).													
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.													
Printed/Typed Name <b>Jeene Hobbs</b>								Signature <i>Jeene Hobbs</i>		Date <b>5 14 85</b>			
17. Transporter 1 Acknowledgement of Receipt of Materials								Signature		Date			
Printed/Typed Name								Signature		Date			
18. Transporter 2 Acknowledgement of Receipt of Materials								Signature		Date			
Printed/Typed Name <b>LANCE G DAVIS</b>								Signature <i>Lance G Davis</i>		Date <b>5 14 85</b>			
19. Discrepancy Indication Space													
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.													
Printed/Typed Name <b>D E Phelps</b>								Signature <i>D E Phelps</i>		Date <b>5 14 85</b>			

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>WA 789 000 8967</b>		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.									
		3. Generator's Name and Mailing Address <b>RD Hensyol 337/300 Area w/B-79</b>		<b>WHC 12-41B</b>		A. State Manifest Document Number		B. State Generator's ID									
4. Generator's Phone (509) <b>376-3743</b>		5. Transporter 1 Company Name <b>Rockwell Hanford</b>		6. US EPA ID Number <b>WA 789 000 8967</b>		C. State Transporter's ID		D. Transporter's Phone <b>376-1420</b>									
7. Transporter 2 Company Name <b>NA</b>		8. US EPA ID Number <b>NA</b>		E. State Transporter's ID		F. Transporter's Phone		G. State Facility's ID									
9. Designated Facility Name and Site Address <b>Central Landfill Chemical Trench</b>		10. US EPA ID Number <b>WA 789 000 8967</b>		H. Facility's Phone <b>(509) 376-6748</b>													
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers		13. Total Quantity		14. Unit Wt/Vol		15. Waste No.					
						No. Type											
						a. <b>Non Regulated Empty Oil Drums</b>		<b>None</b>		<b>None</b>		<b>25 DM</b>		<b>182 ft<sup>3</sup></b>		<b>None</b>	
						b.											
						c.											
d.																	
J. Additional Descriptions for Materials Listed Above  <b>No hazardous material</b>						K. Handling Codes for Wastes Listed Above											
15. Special Handling Instructions and Additional Information																	
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.																	
Printed/Typed Name <b>RD Hensyol</b>						Signature <b>RD Hensyol</b>						Date <b>12/18/84</b>					
17. Transporter 1 Acknowledgement of Receipt of Materials						Approved by <b>LJ Lust</b>						Date <b>12/18/84</b>					
Printed/Typed Name <b>Timothy W Tokers</b>						Signature <b>Timothy W Tokers</b>						Date <b>4/30/85</b>					
18. Transporter 2 Acknowledgement of Receipt of Materials						Signature						Date					
Printed/Typed Name						Signature						Date					
19. Discrepancy Indication Space																	
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.																	
Printed/Typed Name <b>D E Phelps</b>						Signature <b>D E Phelps</b>						Date <b>4/30/85</b>					

000286

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>WA 789 000 8967</b>		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.							
3. Generator's Name and Mailing Address <b>RD Hensydel 337/300 Area w/B-77</b>						A. State Manifest Document Number									
						B. State Generator's ID									
4. Generator's Phone (509) <b>376-3743</b>						C. State Transporter's ID									
5. Transporter 1 Company Name <b>Rockwell Hanford</b>				6. US EPA ID Number <b>WA 789 000 8967</b>		D. Transporter's Phone <b>376-1420</b>									
7. Transporter 2 Company Name <b>NA</b>				8. US EPA ID Number <b>NA</b>		E. State Transporter's ID									
9. Designated Facility Name and Site Address <b>Central Landfill Chemical Treatment</b>						F. Transporter's Phone									
						G. State Facility's ID									
10. US EPA ID Number <b>WA 789 000 8967</b>						H. Facility's Phone <b>(509) 376-6745</b>									
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers		13. Total Quantity		14. Unit Weight		15. Waste No.			
						No.		Type							
a. <b>Non Regulated Empty Oil Drums</b> <b>None</b> <b>None</b>						<b>25</b>		<b>DA</b>		<b>132</b>		<b>ft<sup>3</sup></b>		<b>None</b>	
b.															
c.															
d.															
16. Additional Descriptions for Materials Listed Above <b>No hazardous material</b>						K. Handling Codes for Wastes Listed Above									
15. Special Handling Instructions and Additional Information															
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.															
Printed/Typed Name <b>RD Hensydel</b>						Signature <b>RD Hensydel</b>						Date <b>12/18/84</b>			
17. Transporter 1 Acknowledgement of Receipt of Materials						Printed/Typed Name <b>Timothy W. Tokery</b>						Signature <b>Timothy W. Tokery</b>		Date <b>4/2/85</b>	
18. Transporter 2 Acknowledgement of Receipt of Materials						Printed/Typed Name						Signature		Date	
19. Discrepancy Indication Space															
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						Date									
Printed/Typed Name <b>D E Phelps</b>						Signature <b>D E Phelps</b>						Date <b>4/2/85</b>			

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>WA 789 000 8967</b>		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.					
3. Generator's Name and Mailing Address <b>J. R. Cooper 1114 N/ 100 N Area</b>						A. State Manifest Document Number							
						B. State Generator's ID							
4. Generator's Phone ( 509 ) <b>373-4939</b>						C. State Transporter's ID							
5. Transporter 1 Company Name <b>Rockwell Hanford</b>						D. Transporter's Phone <b>376-1420</b>							
6. US EPA ID Number <b>WA 789 000 8967</b>						E. State Transporter's ID							
7. Transporter 2 Company Name <b>NA</b>						F. Transporter's Phone							
8. US EPA ID Number <b>NA</b>						G. State Facility's ID							
9. Designated Facility Name and Site Address <b>Central Landfill Corrosive Trench</b>						H. Facility's Phone <b>(509) 376-6748</b>							
10. US EPA ID Number <b>WA 789 000 8967</b>													
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers		13. Total Quantity		14. Unit Wt/Vol		15. Waste No.	
						No. Type							
a. <b>Non-regulated drums of oil-soaked soil</b> <b>None</b> <b>None</b>						<b>12</b> <b>DM</b>		<b>88</b>		<b>Ft<sup>3</sup></b>		<b>None</b>	
b.													
c.													
d.													
J. Additional Descriptions for Materials Listed Above						K. Handling Codes for Wastes Listed Above							
15. Special Handling Instructions and Additional Information													
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.													
Printed/Typed Name <b>JR COOPER</b>						Signature <i>JR Cooper</i>		Certified by <b>L. F. Lust</b>		Date <b>4/13/85</b>			
17. Transporter 1 Acknowledgement of Receipt of Materials						Signature <i>Timothy W Toberg</i>		Date <b>4/15/85</b>					
Printed/Typed Name <b>Timothy W Toberg</b>						Signature <i>Timothy W Toberg</i>		Date <b>4/15/85</b>					
18. Transporter 2 Acknowledgement of Receipt of Materials						Signature		Date					
Printed/Typed Name						Signature		Date					
19. Discrepancy Indication Space													
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.													
Printed/Typed Name <b>D E Phelps</b>						Signature <i>D E Phelps</i>		Date <b>4/15/85</b>					

000288

<b>Rockwell Hanford Operations</b>		<b>DANGEROUS WASTE TREATMENT, STORAGE AND DISPOSAL RECORD</b>					
<b>STORAGE/DISPOSAL ACTIVITY</b>					<b>ORIGINATOR</b>		
Onsite Disposal (D81): <input type="checkbox"/> Oxidizer Trench    WHC 12-13 <input checked="" type="checkbox"/> Corrosive Trench <input type="checkbox"/> Asbestos Trench					End Function:		Manifest Number: WHC 12-13
					Company: WHC		Building/Area W/B-17
Non-PCB Onsite Storage (SO1)/Offsite TSD: <input type="checkbox"/>					Contact Person:		
PCB Onsite Storage/Offsite Disposal: <input type="checkbox"/>					Address/Phone:		
<b>PHYSICAL DESCRIPTION</b>							
Item No.	Description Of Waste	DOT Hazard Class	W DOE DW Number(s)	Weight (KG)	Volume Of Waste and Container (FT <sup>3</sup> )		Generating Facility Bldg./Area
1	Tinpsit® LT-26	Poison B	WT02	4.3	2.5		326/300
2	(contains 50 wt% Thiourea.)						
3	contains 185 lbs.						
4							
5							
6							
7							
8							
9							
10							
For additional items, continue on the back of this form.				Total Weight (Front & Back) _____ KG		Total Volume (Front & Back) _____ FT <sup>3</sup>	
<b>TREATMENT, STORAGE, AND DISPOSAL INFORMATION (To be completed by Rockwell)</b>							
ONSITE DISPOSAL: LAND FILL		Disposal Date: 4-4-1985		Signature: Disposer <i>W E Phelps</i>			
		Trench Location: CORROSIVE Trench		Beginning Coordinates: N		W	
		Ending Coordinates: N		W			
NON PCB OFFSITE DISPOSAL		Storage Time:		Arrival Date:			
		Offsite TSD		Date Shipped:			
				Facility Name:			
				Facility Address:			
				TSD Process:		Landfill (D81): <input type="checkbox"/> Disposal Date	
				Treatment (TO _____): <input type="checkbox"/> Treatment Date			
				Specify Treatment Activity			
				Other ( _____ ): <input type="checkbox"/>			
				Specify Activity			
PCB OFFSITE DISPOSALS		Storage Time:		Beginning Date:			
		Offsite Disposal:		Date Shipped:			
				Facility Name:			
				Facility Address:			
COMMENTS:							

000289

A-6400-249 (11-84)

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. WA 789-000-8967		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.					
3. Generator's Name and Mailing Address R. D. Hensyel 337/300 Area WWA-79						WHC 12-13							
4. Generator's Phone (509) 376-3743						A. State Manifest Document Number							
5. Transporter 1 Company Name Rockwell Hanford						B. State Generator's ID							
6. US EPA ID Number WA 789-000-8967						C. State Transporter's ID							
7. Transporter 2 Company Name						D. Transporter's Phone 376-1420							
8. US EPA ID Number						E. State Transporter's ID							
9. Designated Facility Name and Site Address Central Landfill Corrosive Trench						F. Transporter's Phone							
10. US EPA ID Number WA 789-000-8967						G. State Facility's ID							
						H. Facility's Phone (509) 376-6748							
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers		13. Total Quantity		14. Unit Wt/Vol		15. Waste No.	
a. Waste Poisonous Solid, H.O.S. Poison B UN 2811						1 No. M Type		2.5		Ft <sup>3</sup>		WT02	
b.													
c.													
d.													
J. Additional Descriptions for Materials Listed Above Lab pak containing 3 containers (7 pints) of Tinposit R LT-26						K. Handling Codes for Wastes Listed Above							
15. Special Handling Instructions and Additional Information													
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.													
Printed/Typed Name R D Hensyel						Signature R D Hensyel						Date Month Day Year	
17. Transporter 1 Acknowledgement of Receipt of Materials						Signature Joe Aldridge						Date Month Day Year	
Printed/Typed Name Joe Aldridge						Signature Joe Aldridge						Date Month Day Year	
18. Transporter 2 Acknowledgement of Receipt of Materials						Signature						Date Month Day Year	
Printed/Typed Name						Signature						Date Month Day Year	
19. Discrepancy Indication Space													
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.													
Printed/Typed Name D E Phelps						Signature D E Phelps						Date Month Day Year	
												Date Month Day Year	

000290

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>WA 789-000-8967</b>		Manifest Document No.		2. Page 1 of <b>1</b>		Information in the shaded areas is not required by Federal law.							
3. Generator's Name and Mailing Address <b>R. D. Hensy 337/300 Area WA-79</b>						A. State Manifest Document Number <b>WHC 12-13</b>									
4. Generator's Phone ( <b>509</b> ) <b>376-3743</b>						B. State Generator's ID									
5. Transporter 1 Company Name <b>Rockwell Hanford</b>				6. US EPA ID Number <b>WA 789-000-8967</b>		C. State Transporter's ID									
7. Transporter 2 Company Name				8. US EPA ID Number		D. Transporter's Phone <b>376-1420</b>									
9. Designated Facility Name and Site Address <b>Central Landfill Corrosive Trench</b>				10. US EPA ID Number <b>WA 789-000-8967</b>		E. State Transporter's ID									
						F. Transporter's Phone									
						G. State Facility's ID									
						H. Facility's Phone <b>(509) 376-6748</b>									
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers		13. Total		14. Unit		15. Waste No.			
						No. Type		Quantity		Wt/Vol					
						a. <b>Waste Poisonous Poison B UN 2811</b>		<b>1 M</b>		<b>7.5</b>		<b>Ft<sup>3</sup></b>		<b>WT02</b>	
						b.									
						c.									
d.															
J. Additional Descriptions for Materials Listed Above <b>Lab pak containing 3 containers (7 pints) of Tinposit R LT-26</b>						K. Handling Codes for Wastes Listed Above									
15. Special Handling Instructions and Additional Information <i>Please Note: This material was transferred to 2727-5 per MANIFEST 12-13 Part 2 Jan</i>															
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.															
Printed/Typed Name <i>R. D. Hensy</i>						Signature <i>[Signature]</i>		Date Month Day Year							
17. Transporter 1 Acknowledgement of Receipt of Materials						Signature		Date Month Day Year							
18. Transporter 2 Acknowledgement of Receipt of Materials						Signature		Date Month Day Year							
19. Discrepancy Indication Space															
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.															
Printed/Typed Name <i>[Signature]</i>						Signature <i>[Signature]</i>		Date Month Day Year <i>12/1/85</i>							

DATE	NO	NO
3/11		
NO	NO	NO
ACT	NO	
REPLY	DUE	
DIST.	ENC.	APPL.
Ash, E.B.		
Bartholomew, D.C.		
Bellotatto, M.		
Carey, J.M.		
Crawford, A.C.	✓	
Deichman, J.L.		
Di Pol, C.V.		
Donahue, J.W.		
Gimera, R.J.		
Gruha, R.S.		
Hammond, R.D.		
Heineman, R.E.		
Kinzer, J.E.		
Knight, B.E.	✓	
Larson, M.P.		
Lorenzini, P.G.	✓	
Madock, R.G.		
McDermott, R.J.		
Ogletree, L.R.		
Pascoe, K.I.		
Patterson, J.W.	✓	
Perkins, J.O.		
Reiser, A.L.		
Roecker, J.H.	✓	
Selina, C.M.		
Weil, V.R.		
Zahn, L.L.		
Contract Administrator	✓	
Central Files	✓	
DR	✓	
Groth	✓	
CH	✓	
Rodgers	✓	
LF	✓	
Lust	✓	
GR	✓	
Cox GRC	✓	
AD	✓	
Beer	✓	
DD	✓	
Wendrich	✓	
WF	✓	
Heine	✓	
HA	✓	
Haerer	✓	
DE	✓	
Phelps	✓	
CC	✓	
MSADE	✓	
DATE	NO	NO
OCT 8 4 1984		
54-6000-117		

Rockwell Hanford Operations  
Energy Systems Group  
P.O. Box 800  
Richland, WA 99352



Rockwell  
International

has BEN completed  
IN CORROSIVE TRENCH

4-4-1985

OCT 24 1984

In reply, refer to letter R84-3799

Mr. F. M. Smith  
W/B-17  
Westinghouse Hanford Company  
Post Office Box 1970  
Richland, Washington 99352

Dear Mr. Smith:

DISPOSAL ANALYSIS NO. 12-13

Reference: Chemical Waste Disposal Request, October 17, 1984

The Solid Waste Processing and Disposal Unit (SWP&DU) of Rockwell Hanford Operations (Rockwell) has completed analysis of the reference Chemical Waste Disposal Request. Disposal instructions for these wastes are prescribed in the attached, subject Disposal Analysis.

All packaging, labeling and marking of the waste must be completed in accordance with the prescribed instructions, which are based on Department of Transportation (DOT) regulations 49 CFR 171-179. In accordance with 40 CFR 263, a properly completed Uniform Hazardous Waste Manifest is required to accompany all waste shipments. A partially completed manifest is attached for your use.

After packaging, labeling and marking have been completed by the waste generator, inspection of the waste packages will be made by SWP&DU personnel as required to certify that the waste is prepared in the manner designated in the subject Disposal Analysis. After inspection, an SWP&DU representative will sign the manifest. Failure of the generator to comply with the instructions in the subject Disposal Analysis will result in suspension of disposal privileges for the offending facility.

Arranging for transporting waste packages directly to the Hanford Nonradioactive Hazardous Waste Disposal Trench is a generator responsibility and may be implemented following compliance with the disposal instructions for Onsite Disposal in the subject Disposal Analysis, completion of the manifest and certification by SWP&DU. Transportation arrangements can be made by contacting A. D. Poor (6-1420).

000292



Rockwell  
International

Mr. F. M. Smith

Page 2

OCT 24 1984

Should you require further assistance regarding the disposition of the wastes listed on the subject Disposal Analysis, please contact Mr. L. F. Lust (3-4802).

Very truly yours,

*H. A. Haerer*

H. A. Haerer, Project Manager  
Hazardous Waste Program

HAH:LFL:ra

Att.

000293

DISPOSAL ANALYSIS NO. 12-13

Onsite Disposal

Items listed for Onsite Disposal must be properly packaged, labeled and manifested for disposal at the Hanford Nonradioactive Hazardous Waste Chemical Trench.

The waste generator must comply with the following requirements for packaging, labeling and marking wastes for onsite disposal:

- o In accordance with 49 CFR 173.24, waste must be packaged in strong, tight DOT-approved containers. The use of a sealed, steel drum is recommended. The containers of waste should be packed in the drum, completely surrounded and cushioned with absorbent material (e.g., "kitty litter" or vermiculite).
- o The enclosed DOT label, as specified in this Disposal Analysis, must be applied to the container.
- o The DOT Shipping Name and the DOT Identification Number specified in this Disposal Analysis must be marked on the container.
- o The weight of the container, if over 110 pounds, must be marked on the container.
- o In accordance with 49 CFR 172.301 and 172.304, all marking must be legible, durable, in letters at least one-half inch high and in a color which contrasts with the container.
- o Bungs must be securely in place for transport.

All hazardous waste must be accompanied by a Uniform Hazardous Waste Manifest. The manifest has been initiated by the Rockwell Solid Waste Processing and Disposal Unit (SWP&DU). Both the waste generator and a representative from SWP&DU will sign the Generator's Certification block 16. After block 17 has been signed by the transporter and block 20 has been signed by the disposal site operator, the manifest will be returned to SWP&DU, 2750-E 200 East for distribution of the copies.

000294

DISPOSAL ANALYSIS NO. 12-13

ITEM NO.	CONTAINER NO.	DOT SHIPPING NAME	DOT HAZARD CLASS	DOT IDENTIFICATION NUMBER	DOT LABEL	EPA NUMBER	NO. OF CONTAINERS	TYPE OF CONTAINER	QUANTITY PER CONTAINER
-------------	------------------	-------------------------	------------------------	---------------------------------	--------------	---------------	----------------------	----------------------	------------------------------

OFFSITE DISPOSALONSITE DISPOSAL

Waste Poisonous Solid, NOS	Poison B	UN2811	Poison	None	3	Polyethylene	7 pints
----------------------------------	----------	--------	--------	------	---	--------------	---------

000295

000000

M A T E R I A L   S A F E T Y   D A T A   S H E E T S

Shipley Company Inc.  
2300 Washington Street  
Newton, Massachusetts 02162  
Emergency Phone: (617) 969-5500

EFFECTIVE DATE: 17 Jan. 1984

PRODUCT NAME: TINPOSIT® LT-26

Powdered Tin

DOT CLASS: Not regulated

SECTION I - HAZARDOUS MIXTURES

INGREDIENT (TYPICAL VALUES - NOT SPECIFICATIONS)	PERCENT	TLV
Tin (from stannous chloride)	9	2mg/M <sup>3</sup>
Thiourea	50	
Proprietary Ingredients ( <i>che/ates</i> )	41	

Including Water, not deemed hazardous per OSHA definition.

SECTION II - PHYSICAL DATA

BOILING POINT(°F): N.A.	SPECIFIC GRAVITY (H <sub>2</sub> O=1): N.A.
VAPOR PRESSURE(mmHg): N.A.	% VOLATILE BY VOL.: N.A.
VAPOR DENSITY(Air=1): N.A.	EVAPORATION RATE: N.A.
SOLUBILITY IN WATER: Moderate	
APPEARANCE AND ODOR: A granular, greyish white powder with sulfidic odor.	

SECTION III - FIRE AND EXPLOSION HAZARD DATA

FLASH POINT: Non-flammable	FLAMMABLE LIMITS:
METHOD USED:	
EXTINGUISHING MEDIA: Water, CO <sub>2</sub> , Dry chemical	
SPECIAL FIRE FIGHTING PROCEDURES: Check for presence of toxic fumes of phosphine and oxides of phosphorous.	
UNUSUAL FIRE AND EXPLOSION HAZARDS: Heating to decomposition can cause emission of toxic fumes and spontaneous ignition of the dry salts.	

SECTION IV - REACTIVITY DATA

STABILITY: Stable

CONDITIONS TO AVOID: Do not store near oxidizing agents.

INCOMPATIBILITY: Oxidizing agents

HAZARDOUS DECOMPOSITION: If heated to decomposition, toxic fumes of phosphine and oxides of phosphorus can be emitted.

HAZARDOUS POLYMERIZATION: Will not occur

000297

M A T E R I A L S A F E T Y D A T A S H E E T  
Shipley Company Inc., Newton, Massachusetts 02162  
Emergency Phone: (617) 969-5500  
TINPOSIT® LT-26

-----  
SECTION V - SPILL, LEAK AND DISPOSAL PROCEDURES

ACTION TO TAKE FOR SPILLS: Flush area with cold water into Waste Treatment System  
DISPOSAL METHOD: Contact Shipley Technical Services Department

-----  
SECTION VI - HEALTH HAZARD DATA

INGESTION: Contact Physician immediately  
EYE CONTACT: Flush with water for 15 minutes--contact physician  
SKIN CONTACT: Flush with copious amounts of water  
INHALATION: Move to fresh air  
EFFECT OF OVEREXPOSURE: May cause allergic skin eruptions

-----  
SECTION VII - SPECIAL PROTECTION INFORMATION

VENTILATION: Local exhaust  
RESPIRATORY PROTECTION: Dust Mask  
PROTECTIVE CLOTHING: Chemical gloves, suitable protective clothing  
EYE PROTECTION: Chemical goggles

-----  
SECTION VIII - SPECIAL PRECAUTIONS AND ADDITIONAL INFORMATION

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING: Treat as an acidic salt and reducing agent. Store in a dry area at 50-90°F. Do not store in direct sunlight. Keep container closed when not in use.

N.A. denotes non-applicable

The Information and recommendations contained herein are believed to be accurate. However, no guarantee or warranty, expressed or implied, is given.

000298

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <u>WIA 739 DIXIE 967</u>		Manifest Document No.		2. Page <u>1</u> of <u>1</u>		Information in the shaded areas is not required by Federal law.		
		3. Generator's Name and Mailing Address <u>DELTA TRASH</u> <u>202A / 200E TRASH</u>		A. State Manifest Document Number		B. State Generator's ID				
4. Generator's Phone ( <u>504</u> ) <u>373-2227</u>		6. US EPA ID Number		C. State Transporter's ID		D. Transporter's Phone <u>724-1-70</u>				
5. Transporter 1 Company Name <u>DELTA TRASH</u>		7. Transporter 2 Company Name		E. State Transporter's ID		F. Transporter's Phone				
9. Designated Facility Name and Site Address <u>DELTA TRASH</u>		10. US EPA ID Number		G. State Facility's ID		H. Facility's Phone <u>724-1-70</u>				
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)		12. Containers		13. Total Quantity		14. Unit Wt/Vol		15. Waste No.		
		No.	Type							
		a.	<u>2</u>	<u>FB</u>	<u>—</u>		<u>—</u>		<u>16.000</u>	
		b.								
		c.								
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above								
15. Special Handling Instructions and Additional Information										
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.										
Printed/Typed Name				Signature <u>Ronald J. [Signature]</u>				Date Month Day Year <u>4</u> <u>2</u> <u>55</u>		
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature <u>[Signature]</u>				Date Month Day Year <u>4</u> <u>2</u> <u>55</u>		
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature <u>[Signature]</u>				Date Month Day Year <u>4</u> <u>2</u> <u>55</u>		
19. Discrepancy Indication Space										
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.										
Printed/Typed Name <u>D. F. Phillips</u>				Signature <u>[Signature]</u>				Date Month Day Year <u>1</u> <u>1</u> <u>55</u>		

POOR COPY RECEIVED

000299

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>WA 789 000 8967</b>		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.					
3. Generator's Name and Mailing Address <b>RH Smith 105 N/125/100 N</b>						A. State Manifest Document Number							
4. Generator's Phone (509) <b>373-4940</b>						B. State Generator's ID							
5. Transporter 1 Company Name <b>Rockwell Hanford</b>						C. State Transporter's ID							
6. US EPA ID Number <b>WA 789 000 8967</b>						D. Transporter's Phone <b>376-1420</b>							
7. Transporter 2 Company Name						E. State Transporter's ID							
8. US EPA ID Number						F. Transporter's Phone							
9. Designated Facility Name and Site Address <b>Central Landfill Corrosive Trench</b>						G. State Facility's ID							
10. US EPA ID Number <b>WA 789 000 8967</b>						H. Facility's Phone <b>(509) 378-6748</b>							
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers		13. Total Quantity		14. Unit Wt/Vol		15. Waste No.	
a. <b>Waste Methyl Flammable Ethyl Ketone Liquid UN 1193</b>						No. <b>11</b> Type <b>DM</b>		<b>80</b>		<b>3</b>		<b>0001</b>	
b.													
c.													
d.													
J. Additional Descriptions for Materials Listed Above <b>11 55-gal steel drums, empty</b>						K. Handling Codes for Wastes Listed Above							
15. Special Handling Instructions and Additional Information													
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.													
Printed/Typed Name <b>KENNETH H SMITH</b>						Signature <i>[Signature]</i>		Date <b>1 23 85</b>					
17. Transporter 1 Acknowledgement of Receipt of Materials						Signature <i>J. A. Aldridge</i>		Date <b>1 23 85</b>					
18. Transporter 2 Acknowledgement of Receipt of Materials						Signature		Date					
19. Discrepancy Indication Space													
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						Signature <i>D E Phelps</i>		Date <b>1 23 85</b>					

000300

<b>Rockwell Hanford Operations</b>		<b>DANGEROUS WASTE TREATMENT, STORAGE AND DISPOSAL RECORD</b>					
<b>STORAGE/DISPOSAL ACTIVITY</b>				<b>ORIGINATOR</b>			
Onsite Disposal (D81): <input type="checkbox"/> Oxidizer Trench <input checked="" type="checkbox"/> Corrosive Trench <input type="checkbox"/> Asbestos Trench				End Function: <i>PK</i>		Manifest Number: <i>RHO 13-33</i>	
Non-PCB Onsite Storage (SOI)/Offsite TSD: <input type="checkbox"/> PCB Onsite Storage/Offsite Disposal: <input type="checkbox"/>				Company: <i>RHO</i>		Building/Area: <i>202A / 200 East</i>	
				Contact Person: <i>RL Nelson</i>			
				Address/Phone: <i>202A / 200 East</i>			
<b>PHYSICAL DESCRIPTION</b>							
Item No.	Description Of Waste	DOT Hazard Class	W DOE DW Number(s)	Weight (KG)	Volume Of Waste and Container (FT <sup>3</sup> )	Generating Facility Bldg./Area	
1	<i>Waste Non-regulated empty drums (7)</i>	<i>None</i>	<i>None</i>	<i>223</i>	<i>51</i>	<i>202A / 200 East</i>	
2							
3							
4							
5							
6							
7							
8							
9							
10							
For additional items, continue on the back of this form.				Total Weight (Front & Back) <i>223</i> KG		Total Volume (Front & Back) <i>51</i> FT <sup>3</sup>	
<b>TREATMENT, STORAGE, AND DISPOSAL INFORMATION (To be completed by Rockwell)</b>							
ONSITE DISPOSAL: <i>Central Landfill</i>		Disposal Date: <i>1-16-85</i>		Signature: Disposer <i>[Signature]</i>			
Trench Location: <i>19N</i>		Beginning Coordinates: N <i>115</i> W <i>19N</i> Ending Coordinates: N <i>120</i> W <i>19N</i>					
NON PCB OFFSITE DISPOSAL		Storage Time: Offsite TSD		Arrival Date: Date Shipped: Facility Name: Facility Address: TSD Process:			
				Landfill (D81): <input type="checkbox"/> Disposal Date Treatment (TO ____): <input type="checkbox"/> Treatment Date Specify Treatment Activity Other ( ____ ): <input type="checkbox"/> Specify Activity			
PCB OFFSITE DISPOSALS		Storage Time: Offsite Disposal:		Beginning Date: Date Shipped: Facility Name: Facility Address:			
COMMENTS: <i>See item B, Uniform Hazardous Waste Manifest, RHO 13-33, oxidizer drum, 30 gal</i>							

<b>STORAGE/DISPOSAL ACTIVITY</b>		<b>ORIGINATOR</b>	
Onsite Disposal (D81):	<input type="checkbox"/> Oxidizer Trench <input checked="" type="checkbox"/> Corrosive Trench <input type="checkbox"/> Asbestos Trench	End Function: <b>PK</b>	Manifest Number: <b>RHO 13-33</b>
		Company: <b>RHO</b>	Building/Area: <b>202A / 200 East</b>
Non-PCB Onsite Storage (SOI)/Offsite TSD: <input type="checkbox"/>		Contact Person: <b>RL Nelson</b>	
PCB Onsite Storage/Offsite Disposal: <input type="checkbox"/>		Address/Phone: <b>202A / 200 East</b>	

## PHYSICAL DESCRIPTION

Item No.	Description Of Waste	DOT Hazard Class	WDOE DW Number(s)	Weight (KG)	Volume Of Waste and Container (FT <sup>3</sup> )	Generating Facility Sldg./Area
1	Waste Non-regulated empty drums (7)	None	None	223	51	202A/200 East
2						
3						
4						
5						
6						
7						
8						
9						
10						

For additional items, continue on the back of this form.

Total Weight (Front & Back) **223 KG**      Total Volume (Front & Back) **51 FT<sup>3</sup>**

## TREATMENT, STORAGE, AND DISPOSAL INFORMATION (To be completed by Rockwell)

<b>ONSITE DISPOSAL:</b> <b>Central Landfill</b>		Disposal Date: <b>1-16-85</b>		Signature: Disposer <b>T.R. Gendry</b>	
Trench Location: <b>19N</b>		Beginning Coordinates: N <b>115</b> W <b>19N</b>		Ending Coordinates: N <b>120</b> W <b>19N</b>	
<b>NON PCB OFFSITE DISPOSAL</b>		Storage Time:	Arrival Date:		
			Date Shipped:		
		Offsite TSD	Facility Name:		
			Facility Address:		
			TSD Process:		
			Landfill (D81): <input type="checkbox"/> Disposal Date		
			Treatment (TO ____): <input type="checkbox"/> Treatment Date		
			Specify Treatment Activity		
			Other (____): <input type="checkbox"/>		
			Specify Activity		
<b>PCB OFFSITE DISPOSALS</b>		Storage Time:	Beginning Date:		
			Date Shipped:		
		Offsite Disposal:	Facility Name:		
			Facility Address:		

## COMMENTS:

See item B, Uniform Hazardous Waste Manifest, RHO 13-33, Oxidizer  
1 drum, 30 gal

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>WA 789 000 8967</b>		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.		
3. Generator's Name and Mailing Address <b>RL Nelson 202A 200 East RHO 13-33</b>						A. State Manifest Document Number				
						B. State Generator's ID				
4. Generator's Phone (509) 373-2323						C. State Transporter's ID				
5. Transporter 1 Company Name <b>Rockwell Hanford</b>						D. Transporter's Phone 376-1420				
6. US EPA ID Number <b>WA 789 000 8967</b>						E. State Transporter's ID				
7. Transporter 2 Company Name <b>WA</b>						F. Transporter's Phone				
8. US EPA ID Number <b>NA</b>						G. State Facility's ID				
9. Designated Facility Name and Site Address <b>Central Land Fill Corrosive Trench</b>						H. Facility's Phone <b>(509) 376-6748</b>				
10. US EPA ID Number <b>WA 789 000 8967</b>										
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers		13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
						No.	Type			
a. <b>Non-regulated empty drums. waste. None None</b>						<b>7</b>	<b>DM</b>	<b>51</b>	<b>Fe<sup>3</sup></b>	<b>None</b>
b. <b>EMPTY DRUMS CORROSIVE 15 OXIDIZER 309AL 1</b>										
c.										
d.										
J.. Additional Descriptions for Materials Listed Above						K. Handling Codes for Wastes Listed Above				
15. Special Handling Instructions and Additional Information										
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.										
Printed/Typed Name <b>RONALD L. NELSON</b>						Signature <i>Ronald L. Nelson</i>		Date <b>1/16/85</b>		
17. Transporter 1 Acknowledgement of Receipt of Materials						Signature <i>J. A. Aldridge</i>		Date <b>1/16/85</b>		
18. Transporter 2 Acknowledgement of Receipt of Materials						Signature		Date		
19. Discrepancy Indication Space										
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						Signature <i>D E Phelps</i>		Date <b>1/16/85</b>		

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>WA 789 000 3967</b>		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.					
3. Generator's Name and Mailing Address <b>RL Nelson 202A 200 East 509 373-2323</b>						A. State Manifest Document Number							
4. Generator's Phone (509) 373-2323						B. State Generator's ID							
5. Transporter 1 Company Name <b>Rockwell Hanford</b>				6. US EPA ID Number <b>WA 789 000 3967</b>		C. State Transporter's ID							
7. Transporter 2 Company Name <b>NA</b>				8. US EPA ID Number <b>NA</b>		D. Transporter's Phone <b>376-1426</b>							
9. Designated Facility Name and Site Address <b>Central Landfill Corrosive Trench</b>						E. State Transporter's ID							
10. US EPA ID Number <b>WA 789 000 3967</b>						F. Transporter's Phone							
						G. State Facility's ID							
						H. Facility's Phone <b>(509) 376-6748</b>							
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers		13. Total Quantity		14. Unit Wt/Vol		15. Waste No.	
						No.	Type						
a. <b>Non-regulated empty drums, waste. None None</b>						<b>7</b>	<b>DM</b>	<b>51</b>		<b>ft<sup>3</sup></b>		<b>None</b>	
b. <b>Empty drums Corrosive 15</b>													
c. <b>Oxidizer 309AL 1</b>													
d.													
J. Additional Descriptions for Materials Listed Above						K. Handling Codes for Wastes Listed Above							
15. Special Handling Instructions and Additional Information						<b>— R. J. Anderson</b>							
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.										Certified by			
Printed/Typed Name <b>RONALD L. NELSON</b>						Signature <b>Ronald L. Nelson</b>				Date <b>1/16/85</b>			
17. Transporter 1 Acknowledgement of Receipt of Materials						Signature <b>J. A. Aldridge</b>				Date <b>1/16/85</b>			
18. Transporter 2 Acknowledgement of Receipt of Materials						Signature				Date			
19. Discrepancy Indication Space													
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.										Date			
Printed/Typed Name <b>D E Phelps</b>						Signature <b>D E Phelps</b>				Date <b>1/16/85</b>			

000304

<b>Rockwell Hanford Operations</b>		<b>DANGEROUS WASTE TREATMENT, STORAGE AND DISPOSAL RECORD</b>					
<b>STORAGE/DISPOSAL ACTIVITY</b>				<b>ORIGINATOR</b>			
Onsite Disposal (D81): <input type="checkbox"/> Oxidizer Trench <input checked="" type="checkbox"/> Corrosive Trench <input type="checkbox"/> Asbestos Trench				End Function: <div style="border: 1px solid black; padding: 2px; text-align: center;">B53100/ G531AA</div>		Manifest Number: <div style="border: 1px solid black; padding: 2px; text-align: center;">RHO 12-21</div>	
Non-PCB Onsite Storage (SO1)/Offsite TSD: <input type="checkbox"/> PCB Onsite Storage/Offsite Disposal: <input type="checkbox"/>				Company: <div style="border: 1px solid black; padding: 2px; text-align: center;">RHO</div>		Building/Area <div style="border: 1px solid black; padding: 2px; text-align: center;">2101M/200 East</div>	
				Contact Person: <div style="border: 1px solid black; padding: 2px; text-align: center;">F. J. Orsag</div>			
				Address/Phone: <div style="border: 1px solid black; padding: 2px; text-align: center;">2101M/200 East 373-2354</div>			
<b>PHYSICAL DESCRIPTION</b>							
Item No.	Description Of Waste	DOT Hazard Class	W DOE DW Number(s)	Weight (KG)	Volume Of Waste and Container (FT <sup>3</sup> )	Generating Facility Bldg./Area	
1	Empty Non-regulated drums (21)	None	None	668	154	2101M/200 East	
2							
3							
4							
5							
6							
7							
8							
9							
10							
For additional items, continue on the back of this form.				Total Weight (Front & Back) <u>668</u> KG	Total Volume (Front & Back) <u>154</u> FT <sup>3</sup>		
<b>TREATMENT, STORAGE, AND DISPOSAL INFORMATION (To be completed by Rockwell)</b>							
<b>ONSITE DISPOSAL:</b>		Disposal Date:		Signature: Disposer			
		Trench Location:		Beginning Coordinates: N W		Ending Coordinates: N W	
<b>NON PCB OFFSITE DISPOSAL</b>		Storage Time:		Arrival Date:			
		Offsite TSD		Date Shipped:			
				Facility Name:			
				Facility Address:			
				TSD Process:		Landfill (D81): <input type="checkbox"/> Disposal Date Treatment (TO ____): <input type="checkbox"/> Treatment Date Specify Treatment Activity  Other (____): <input type="checkbox"/> Specify Activity	
<b>PCB OFFSITE DISPOSALS</b>		Storage Time:		Beginning Date:			
				Date Shipped:			
		Offsite Disposal:		Facility Name:			
				Facility Address:			
<b>COMMENTS:</b>							

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. WA 789 000 8967		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.					
3. Generator's Name and Mailing Address F. J. Orsag 2101M/200 East 373-2354						A. State Manifest Document Number RHO 12-21B							
4. Generator's Phone (509) 373-2354						B. State Generator's ID							
5. Transporter 1 Company Name Rockwell Hanford						C. State Transporter's ID							
6. US EPA ID Number WA 789 000 8967						D. Transporter's Phone 376-1420							
7. Transporter 2 Company Name NA						E. State Transporter's ID							
8. US EPA ID Number NA						F. Transporter's Phone							
9. Designated Facility Name and Site Address Central Landfill Corrosive Trench						G. State Facility's ID							
10. US EPA ID Number WA 789 000 8967						H. Facility's Phone (509) 376-6748							
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers No. Type		13. Total Quantity		14. Unit Wt/Vol		15. Waste No.	
a. Waste Non-regulated empty drums None None						21 DM		153		Ft <sup>3</sup>		None	
b.													
c.													
d.													
J. Additional Descriptions for Materials Listed Above 21 Empty 55 gallon drums.						K. Handling Codes for Wastes Listed Above							
15. Special Handling Instructions and Additional Information													
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.													
Printed/Typed Name F. J. Orsag						Signature <i>F. J. Orsag</i>						Date Month Day Year	
17. Transporter 1 Acknowledgement of Receipt of Materials						Signature <i>Timothy W. Toberg</i>						Date Month Day Year 11/16/85	
18. Transporter 2 Acknowledgement of Receipt of Materials						Signature						Date Month Day Year	
19. Discrepancy Indication Space													
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.													
Printed/Typed Name DE Phelps						Signature <i>DE Phelps</i>						Date Month Day Year 11/16/85	

000306

TRANSPORTER #1

Rockwell Hanford Operations

## DANGEROUS WASTE TREATMENT, STORAGE AND DISPOSAL RECORD

## STORAGE/DISPOSAL ACTIVITY

Onsite Disposal (DB1):

- ☐ Oxidizer Trench  
☒ Corrosive Trench  
☐ Asbestos Trench

Non-PCB Onsite Storage (SO1)/Offsite TSD. ☐PCB Onsite Storage/Offsite Disposal: ☐

## ORIGINATOR

End Function:

KP

Manifest Number:

RHO 13-23

Company:

RHO

Building/Area

202A/200E

Contact Person:

R L Nelson

Address/Phone:

202A/200E 373-2323

## PHYSICAL DESCRIPTION

Item No.	Description Of Waste	DOT Hazard Class	W DOE DW Number(s)	Weight (KG)	Volume Of Waste and Container (FT <sup>3</sup> )	Generating Facility Bldg./Area
1	Non-regulator Empty drums (18)	None	None	609	118	202A/200E
2						
3						
4						
5						
6						
7						
8						
9						
10						

For additional items, continue on the back of this form.

Total Weight  
(Front & Back) 609 KGTotal Volume  
(Front & Back) 118 FT<sup>3</sup>

## TREATMENT, STORAGE, AND DISPOSAL INFORMATION (To be completed by Rockwell)

ONSITE DISPOSAL:

Disposal Date:

Signature: Disposer

Trench Location:

Beginning Coordinates: N

W

Ending Coordinates: N

W

NON PCB OFFSITE DISPOSAL

Storage Time:

Arrival Date:

Date Shipped:

Offsite TSD

Facility Name:

Facility Address:

TSD Process:

Landfill (DB1):

☐ Disposal Date

Treatment (TO \_\_\_\_):

☐ Treatment Date

Specify Treatment Activity

Other (\_\_\_\_):

☐

Specify Activity

PCB OFFSITE DISPOSALS

Storage Time:

Beginning Date:

Date Shipped:

Offsite Disposal:

Facility Name:

Facility Address:

COMMENTS:

000307

A-6400-249 (11 84)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. WA 789 000 8967		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address RL Nelson 202 A/200 East						A. State Manifest Document Number			
4. Generator's Phone (509) 373-2323						B. State Generator's ID			
5. Transporter 1 Company Name Rockwell Munford						6. US EPA ID Number WA 789 000 8967		C. State Transporter's ID	
7. Transporter 2 Company Name NA						8. US EPA ID Number NA		D. Transporter's Phone 376-1420	
9. Designated Facility Name and Site Address Central Landfill Corrosive Trench						10. US EPA ID Number WA 789 000 8967		E. State Transporter's ID	
								F. Transporter's Phone	
								G. State Facility's ID	
								H. Facility's Phone 376-6748	
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers		13. Total Quantity	
						No. Type		14. Unit Wt/Vol	
a. Non-regulated empty drums						16		118	
b.									
c.									
d.									
J. Additional Descriptions for Materials Listed Above						K. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information									
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.									
Printed/Typed Name RONALD L. NELSON						Signature Ronald L. Nelson		Date 1/15/85	
17. Transporter 1 Acknowledgement of Receipt of Materials						Signature J. A. Aldridge		Date 1/15/85	
18. Transporter 2 Acknowledgement of Receipt of Materials						Signature		Date	
19. Discrepancy Indication Space									
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.									
Printed/Typed Name D. E. Phelps						Signature D. E. Phelps		Date 1/15/85	

UNIFORM HAZARDOUS WASTE MANIFEST		Generator's US EPA ID No. WA 789 000 8967		Manifest Document No. RHO-12-43B		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address R. F. Gretzinger 2101M/1414B/200 East				6. US EPA ID Number WA 789 000 8967		A. State Manifest Document Number			
4. Generator's Phone ( )				8. US EPA ID Number NA		B. State Generator's ID			
5. Transporter 1 Company Name Rockwell Hanford				10. US EPA ID Number WA 789 000 8967		C. State Transporter's ID			
7. Transporter 2 Company Name NA						D. Transporter's Phone 376-1420			
9. Designated Facility Name and Site Address Central Landfill Chemical Trench						E. State Transporter's ID			
						F. Transporter's Phone			
						G. State Facility's ID			
						H. Facility's Phone (509) 376-6748			
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers		13. Total Quantity	
						No. Type		Wt/Vol	
a. Waste Non-regulated Empty drums						4 DM		29 Ft <sup>3</sup>	
b.									
c.									
d.									
J. Additional Descriptions for Materials Listed Above 4 Empty drums. Weight 300 pounds Volume 29 Ft <sup>3</sup>						K. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information									
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.									
Printed/Typed Name R. F. Gretzinger				Signature R. F. Gretzinger		Approved by S. J. Hunt		Date Month Day Year 1 17 85	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature J. A. Albridge				Date Month Day Year 1 11 85	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature				Date Month Day Year	
19. Discrepancy Indication Space									
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.									
Printed/Typed Name D. E. Phelps				Signature D. E. Phelps				Date Month Day Year 1 11 85	

000309

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>WA 789 000 8967</b>		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.									
3. Generator's Name and Mailing Address <b>RL Nelson 202A/100 West Rockwell Harbor</b>						A. State Manifest Document Number											
4. Generator's Phone (509) 373-2323						B. State Generator's ID											
5. Transporter 1 Company Name <b>Rockwell Harbor</b>						C. State Transporter's ID											
6. US EPA ID Number <b>WA 789 000 8967</b>						D. Transporter's Phone <b>376-1420</b>											
7. Transporter 2 Company Name						E. State Transporter's ID											
8. US EPA ID Number						F. Transporter's Phone											
9. Designated Facility Name and Site Address <b>Central Landfill Chemical Trench</b>						G. State Facility's ID											
10. US EPA ID Number <b>WA 789 000 8967</b>						H. Facility's Phone <b>(509) 376-6748</b>											
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers		13. Total Quantity		14. Unit WuVol		15. Waste No.					
						No. Type											
						a. <b>Non-regulated</b>		<b>None</b>		<b>None</b>		<b>12 DP 88</b>		<b>FL<sup>3</sup></b>		<b>None</b>	
						b.											
						c.											
d.																	
J. Additional Descriptions for Materials Listed Above						K. Handling Codes for Wastes Listed Above											
15. Special Handling Instructions and Additional Information <b>12 Empty plastic, 55-gal drums</b>																	
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.																	
Printed/Typed Name <b>RONALD L. NELSON</b>						Signature <i>Ronald L. Nelson</i>		Date <b>1/10/85</b>									
17. Transporter 1 Acknowledgement of Receipt of Materials						Signature <i>John Wayne Carr</i>		Date <b>1/10/85</b>									
Printed/Typed Name <b>John Wayne Carr</b>						Signature		Date									
18. Transporter 2 Acknowledgement of Receipt of Materials						Signature		Date									
Printed/Typed Name						Signature		Date									
19. Discrepancy Indication Space																	
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.																	
Printed/Typed Name <b>D E Phelps</b>						Signature <i>D E Phelps</i>		Date <b>1/10/85</b>									

000310

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. WA 789 000 8967	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address TD Cooper 234-5/200 West		RHO-5-31		A. State Manifest Document Number		
4. Generator's Phone (509) 873-2543				B. State Generator's ID		
5. Transporter 1 Company Name Rockwell Hanford		6. US EPA ID Number WA 789 000 8967		C. State Transporter's ID		
7. Transporter 2 Company Name NA		8. US EPA ID Number NA		D. Transporter's Phone 376-1420		
9. Designated Facility Name and Site Address Chemical Trench (Oxidizer) Central Landfill		10. US EPA ID Number WA 789 000 8967		E. State Transporter's ID		
				F. Transporter's Phone		
				G. State Facility's ID		
				H. Facility's Phone (509) 376-6748		
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)		12. Containers	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.	
a. <input type="checkbox"/> HM Oxidizer, Corrosive Oxidizer NA 9194 Solid, NOS		No. 13	Type DM	715 545 eff	G	D002
b. <input type="checkbox"/>						
c. <input type="checkbox"/>						
d. <input type="checkbox"/>						
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above				
15. Special Handling Instructions and Additional Information						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.						
Printed/Typed Name Thurman D. Cooper		Signature Thurman Cooper		Date Certified by Month Day Year		
17. Transporter 1 Acknowledgement of Receipt of Materials		Signature J. A. Aldridge		Date Month Day Year 1 11 85		
18. Transporter 2 Acknowledgement of Receipt of Materials		Signature		Date Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name D E Phelps		Signature D E Phelps		Date Month Day Year 11 11 85		

000311

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>WA 789 000 8967</b>		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.							
3. Generator's Name and Mailing Address <b>RL Nelson 202 A/200 East</b>						A. State Manifest Document Number									
4. Generator's Phone <b>(509) 373-2323</b>						B. State Generator's ID									
5. Transporter 1 Company Name <b>Rockwell Hanford</b>						C. State Transporter's ID									
7. Transporter 2 Company Name <b>NA</b>						D. Transporter's Phone <b>376-1420</b>									
9. Designated Facility Name and Site Address <b>Central Landfill Corrosive Trench</b>						E. State Transporter's ID									
10. US EPA ID Number <b>WA 789 000 8967</b>						F. Transporter's Phone									
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers		13. Total Quantity		14. Unit Wt/Vol		15. Waste No.			
						No. Type									
a. <b>Non-regulated empty drums None None</b>						<b>15 DM</b>		<b>110</b>		<b>Fe<sup>3</sup></b>		<b>None</b>			
b.															
c.															
d.															
J. Additional Descriptions for Materials Listed Above						K. Handling Codes for Wastes Listed Above									
15. Special Handling Instructions and Additional Information															
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.										Certified by				Date	
Printed/Typed Name <b>RONALD L. NELSON</b>						Signature <i>Ronald L. Nelson</i>				Month Day Year <b>1 10 85</b>					
17. Transporter 1 Acknowledgement of Receipt of Materials										Date					
Printed/Typed Name <b>John Wayne Carr</b>						Signature <i>John Wayne Carr</i>				Month Day Year <b>1 10 85</b>					
18. Transporter 2 Acknowledgement of Receipt of Materials										Date					
Printed/Typed Name						Signature				Month Day Year					
19. Discrepancy Indication Space															
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.										Date					
Printed/Typed Name <b>D E Phelps</b>						Signature <i>D E Phelps</i>				Month Day Year <b>11 10 85</b>					

000312

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>WA 789 000 8167</b>		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.		
3. Generator's Name and Mailing Address <b>HA Clark 2721-E/2nd East</b>						A. State Manifest Document Number				
						B. State Generator's ID				
4. Generator's Phone (509) 373-2317						C. State Transporter's ID				
5. Transporter 1 Company Name <b>Rockwell Hanford</b>			6. US EPA ID Number <b>WA 789 000 8167</b>			D. Transporter's Phone <b>376-1426</b>				
7. Transporter 2 Company Name <b>NA</b>			8. US EPA ID Number <b>NA</b>			E. State Transporter's ID				
9. Designated Facility Name and Site Address <b>Central Landfill Chambers Trench</b>			10. US EPA ID Number <b>WA 789 000 8167</b>			F. Transporter's Phone				
						G. State Facility's ID				
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers		13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
						No.	Type			
a. <b>Non-Regulated Empty drums</b> <b>None</b> <b>None</b>						<b>66</b>	<b>DM</b>	<b>450</b>	<b>Ft<sup>3</sup></b>	<b>None</b>
b. <b>Non-Regulated Empty drums</b> <b>None</b> <b>None</b>						<b>4</b>	<b>DF</b>	<b>29</b>	<b>Ft<sup>3</sup></b>	<b>None</b>
c.										
d.										
J. Additional Descriptions for Materials Listed Above <b>66 Metal drums, 4 Fiber Drums Total Volume 511 Ft<sup>3</sup></b>						K. Handling Codes for Wastes Listed Above				
15. Special Handling Instructions and Additional Information										
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.										
Printed/Typed Name <b>H.A. Clark</b>						Signature <b>H.A. Clark</b>		Date <b>Approved by P. J. Hunt</b>		
17. Transporter 1 Acknowledgement of Receipt of Materials						Signature		Date		
Printed/Typed Name						Signature		Month Day Year		
18. Transporter 2 Acknowledgement of Receipt of Materials						Signature		Date		
Printed/Typed Name						Signature		Month Day Year		
19. Discrepancy Indication Space										
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.										
Printed/Typed Name <b>H.A. Clark</b>						Signature <b>H.A. Clark</b>		Date <b>12 14 81</b>		

000313

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: BRET AKERS

Phone Number: 6-6519

Contractor Contracted By: \_\_\_\_\_

Location: 712 BLDG / 700 AREA Estimated Volume (ft<sup>3</sup>): 8 YD

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Bret Akers

Date: 12/20/85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: R E Phillips

Date: 12-23 1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: GREG WOLFE

Phone Number: 376 6519

Contractor Contracted By: \_\_\_\_\_

Location: 712 BLDG Estimated Volume (ft<sup>3</sup>): 600. YC

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: GREG WOLFE 

Date: 12-23-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D E Phelps

Date: 12-23-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: IRA Johnson

Phone Number: 34677

Contractor Contracted By: RHC

Location: 2101M Estimated Volume (ft<sup>3</sup>): 250

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: IRA Johnson

Date: 11-25-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: DE Phelps

Date: 12-10-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: IA Johnson

Phone Number: 34673

Contractor Contracted By: PHO

Location: 284 W Estimated Volume (ft<sup>3</sup>): 200 FT

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: IA Johnson

Date: 11-25-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: DET Phelps

Date: 12 10 - 1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: R. J. Morin RHO

Phone Number: 3-1731

Contractor Contracted By: RHO

Location: 1000 AREA  
1822/1830 BLDG Estimated Volume (ft<sup>3</sup>): 400

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: J. H. Jones CONST.

Date: 11-15

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D. S. [Signature]

Date: 11-14-1980

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: U.S. PARSONS

Phone Number: 373-4000

Contractor Contracted By: R.H.O.

Location: 272-AW Estimated Volume (ft<sup>3</sup>): 100 cu ft

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: J. S. Parson

Date: 11-5-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D. E. Phelps

Date: 11-5-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: R. J. Morin Rits

Phone Number: 3-1721

Contractor Contracted By: RHO

Location: DD AREA 152D/153D Estimated Volume (ft<sup>3</sup>): 500

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: T. A. Evans

Date: 12-31-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D. E. Phelps

Date: 12-31-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: R. L. Morin RHO

Phone Number: 31721

Contractor Contracted By: PHO

Location: 100D AREA/1820/1830 Estimated Volume (ft<sup>3</sup>): 450

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: J.A. JONES CONST.

Date: 10-30-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D E Phelps

Date: 10-30-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: Jerry M. Bishop

Phone Number: 376-3518

Contractor Contracted By: LHC

Location: 313/300 Area Estimated Volume (ft<sup>3</sup>): 270

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Jerry M. Bishop

Date: 10-21-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D E Thelmer

Date: 10-21-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: RHO

Phone Number: 373 2723

Contractor Contracted By: JH Kim

Location: 202A Estimated Volume (ft<sup>3</sup>): 100

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: RHO

Date: 10-15-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: DE Fuchs

Date: 10-15-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: D. L. LANSINK

Phone Number: 3-2231

Contractor Contracted By: RHO

Location: 275 UR Estimated Volume (ft<sup>3</sup>): 200

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: A. T. Tanning

Date: 10-4-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D E Phelps

Date: 10-14-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: Rockwell FRED KAUFER

Phone Number: 3264415

Contractor Contracted By: A. P. Steenma

Location: 1171/400 Estimated Volume (ft<sup>3</sup>): 1.5

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: FF KAUFER

Date: 10-10-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D. E. Phelps

Date: 10-11-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: R. L. Morris RHO

Phone Number: 3-1721

Contractor Contracted By: RHO

Location: 100 D AREA 182 D / 183 D Estimated Volume (ft<sup>3</sup>): 450.00 FT<sup>3</sup>

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: J. A. JONES CONST.

Date: 10-11-1985

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D. E. Phelps

Date: 10-11-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: John M. Dwyer

Phone Number: 376-3510

Contractor Contracted By: UNIC

Location: 313 Estimated Volume (ft<sup>3</sup>): 220

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: John M. Dwyer

Date: 10-8-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D. S. Phelps

Date: 10-8-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: R. L. Moxin

Phone Number: 373-1721

Contractor Contracted By: RHIO

Location: 100B/182 5400 Estimated Volume (ft<sup>3</sup>): 4 to 50.5T

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: J. A. JONES CONSTRUCTION SERVICES INC

Date: 10-7-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: O E P. Moxin

Date: 10-7-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: D. L. LANSING

Phone Number: 3-2231

Contractor Contracted By: RHO

Location: 275 UR Estimated Volume (ft<sup>3</sup>): 250

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: D. L. Lansing

Date: 10-4-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: 10-4-1985

Date: D E Phelps

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: H. L. Moxley

Phone Number: ~~714-371-1521~~ 37-1521

Contractor Contracted By: PHD

Location: 160 B-1 X 2 8-20 Estimated Volume (ft<sup>3</sup>): 350 cf

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: J. A. Jones Construction Services, Inc.

Date: 9-30-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: M. J. [Signature]

Date: 9-30-85

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: R. L. MOXIN RHO

Phone Number: 373-1721

Contractor Contracted By: RHIL

Location: 100B / 147 PLM Estimated Volume (ft<sup>3</sup>): \_\_\_\_\_

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: HAZARDOUS WASTE SEGU CO

Date: \_\_\_\_\_

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: M. J. F. E.

Date: 7-27-85

## HAZARDOUS WASTE MANIFEST

THIS SHIPPING ORDER

must be legibly filled in, in ink, in indelible pencil, or in Carbon, and retained by the Agent.

MANIFEST DOCUMENT NUMBER

JAJ 85-005

TO: T/S/D FACILITY CENTRAL LANDFILL FROM: Generator J. A. Jones Construction Services Co.  
 E.P.A. ID Code No. Address 801 1st St. Richland, WA 99352  
 Destination Origin 300 Area  
 Phone 376-0905

No. Shipping Units	D.O.T. PROPER SHIPPING NAME	HAZARD CLASS	Haz Mat ID No.	EPA Haz Waste No.	WEIGHT	LABELS REQUIRED (or Exemption No.)
4	Asbestos	ORM-C		U013	2750 LB	YES
	Luggers				Per Lugger	

## PLACARDS REQUIRED

NOTE - Where the rate is dependent on value, shippers are required to state specifically in writing the agreed or declared value of the property. The agreed or declared value of the property is hereby specifically stated by the shipper to be not exceeding \$ \_\_\_\_\_ Per \_\_\_\_\_

Subject to Section 7 of the agreement, if this shipment is to be delivered to the consignee without receipt, the carrier shall not make delivery of the shipment without payment of freight and all other charges.

## FREIGHT CHARGES

PREPAID COLLECT

☐ ☐

(Signature of Consignor)

RECEIVED, subject to the classifications and tariffs in effect on the date of the issue of this Bill of Lading, the property described above in apparent good order, except as noted (contents and condition of contents of packages unknown), marked, consigned, and destined as indicated above which said carrier (the word carrier being understood throughout this contract as meaning any person or corporation in possession of the property under the contract) agrees to carry to its usual place of delivery at said destination, if on its route, otherwise to deliver to another carrier on the route to said destination. It is mutually agreed as to each carrier of all or any of said property over all or any portion of said route to destination and as to each party at any time inscribed in all or any said property, that every service to be performed hereunder shall be subject to all the bill of lading terms and conditions in the governing classification on the date of shipment. Shipper hereby certifies that he is familiar with all the bill of lading terms and conditions in the governing classification and the said terms and conditions are hereby agreed to by the shipper and accepted for himself and his assigns.

## ALTERNATE DESTINATION (EMERGENCY ONLY)

## EMERGENCY RESPONSE INFORMATION

T/S/D FACILITY \_\_\_\_\_ CONTACT Name \_\_\_\_\_  
 E.P.A. ID Code No. \_\_\_\_\_ Phone \_\_\_\_\_  
 Address \_\_\_\_\_ National Response Center 1-800-424-8802  
 Destination \_\_\_\_\_ in D. C. 426-2675

## CERTIFICATION

This is to certify that the above named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and the E.P.A.

Generator Signature Ronald Nield Date 9-25-85

TRANSPORTER #1 Timothy W Tokern E.P.A. ID No. \_\_\_\_\_  
 Address 1171 Bldg 1100 AREA  
 City Richland State WA Zip 99352 Phone 509-376-8800

This is to certify acceptance of the hazardous waste shipment.  
 Transporter No. 1 Signature Timothy W Tokern Date 9-26-85

TRANSPORTER #2 \_\_\_\_\_ E.P.A. ID No. \_\_\_\_\_  
 Address \_\_\_\_\_  
 City \_\_\_\_\_ State \_\_\_\_\_ Zip \_\_\_\_\_ Phone \_\_\_\_\_

This is to certify acceptance of the hazardous waste shipment.  
 Transporter No. 2 Signature \_\_\_\_\_ Date \_\_\_\_\_

## TREATMENT/STORAGE/DISPOSAL FACILITY

This is to certify acceptance of the hazardous waste for treatment, storage, or disposal.  
 T/S/D FACILITY Signature M. J. Skelton Date 9-26-85

TRANSPORTER #1 COPY

000332

HAZARDOUS WASTE

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: Dee Prichard/JA Jones Construction Services Company

Phone Number: 376-0895

Contractor Contracted By: J. A. Jones Construction Services Company

Location: 336 Bldg. Estimated Volume (ft<sup>3</sup>): 608

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Ronald Hield

Date: 9-25-85

The above requirements have been met and the estimated volume appears correct.

*MR Jeff Allen*  
9/26/85  
#800977

Landfill Operator: M. J. Elch

Date: 9-26-85

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>WA 789 000 8967</b>		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.	
		3. Generator's Name and Mailing Address <b>Jan Davis</b> <b>1171 Bldg, 1100 Area</b>		6. US EPA ID Number <b>WA 789 000 8967</b>		A. State Manifest Document Number		B. State Generator's ID	
4. Generator's Phone <b>6-3036</b>		7. Transporter 1 Company Name <b>Rockwell Hanford Operations</b>		8. US EPA ID Number <b>1</b>		C. State Transporter's ID		D. Transporter's Phone <b>6-1420</b>	
9. Designated Facility Name and Site Address <b>Central Landfill Asbestos Trench</b>		10. US EPA ID Number <b>WA 789 000 8967</b>		E. State Transporter's ID		F. Transporter's Phone		G. State Facility's ID	
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)		12. Containers No. Type		13. Total Quantity		14. Unit Wt/Vol		1. Waste No.	
a. <b>Asbestos</b>		<b>1</b>		<b>1</b>		<b>CF</b>		<b>U013</b>	
b.									
c.									
d.									
J. Additional Descriptions for Materials Listed Above						K. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information									
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.									
Printed/Typed Name <b>Jan Davis</b>						Signature <b>Jan Davis</b>		Date <b>19 25 85</b>	
17. Transporter 1 Acknowledgement of Receipt of Materials						Printed/Typed Name <b>Timothy W Tobey</b>		Signature <b>Timothy W Tobey</b>	
18. Transporter 2 Acknowledgement of Receipt of Materials						Printed/Typed Name		Signature	
19. Discrepancy Indication Space						Printed/Typed Name		Signature <b>M. J. Echal</b>	
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						Printed/Typed Name		Date <b>17 26 85</b>	

000334

TRANSPORTER #1

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: Jan Davis

Phone Number: 6 3036

Contractor Contracted By: Rockwell Hanford Operations

Location: 71 Bldg 1150 Area Estimated Volume (ft<sup>3</sup>): 1 CF

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Jan Davis

Date: 9-24-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: M. J. Elsh

Date: 9-26-85

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: Lead Bagged

Phone Number: 3-1432

Contractor Contracted By: UNC

Location: 100 H Estimated Volume (ft<sup>3</sup>): 1040

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: J A Jones Construction Services Co

Date: 9-24-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: WJ / Sh

Date: 9-25-85

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: See Prichard/JA Jones Construction Services Company

Phone Number: 376-0895

*Signature*  
= 376-0895

Contractor Contracted By: J. A. Jones Construction Services Company

Location: Longyard 300 Area Estimated Volume (ft<sup>3</sup>): XXXX 456

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Ronald Nield *Handwritten signature*

Date: 9-20-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: M. J. Shuck

Date: 9-24-85

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: R.L. Moxin RHO

Phone Number: 373-1721

Contractor Contracted By: RHO

Location: 100B/182 RUDT Estimated Volume (ft<sup>3</sup>): 350 cu ft

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: J.A. JONES CONSTRUCTION SERV. CO.

Date: 9-23-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: [Signature]

Date: 9-23-85

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: R.L. Moxin RHO

Phone Number: 373-1721

Contractor Contracted By: RHO

Location: 100 B/182 BLDG Estimated Volume (ft<sup>3</sup>): 350 yd

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: J. A. JONES CONSTR. SERV. CO

Date: 9-23-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: M. J. Ehrlich

Date: 9-23-85

# HAZARDOUS WASTE MANIFEST

**THIS SHIPPING ORDER**

must be legibly filled in, in ink, in Indelible Pencil, or in Carbon, and retained by the Agent.

MANIFEST DOCUMENT NUMBER

JAJ 85-004

TO: T/S/D FACILITY **CENTRAL LANDFILL**  
E.P.A. ID Code No. \_\_\_\_\_  
Address \_\_\_\_\_  
Destination \_\_\_\_\_  
Phone \_\_\_\_\_

FROM: Generator **J. A. Jones Construction Services Co.**  
E.P.A. ID Code No. **WA7890008967**  
Address **801 1st St. Richland, WA 99352**  
Origin **300 Area**  
Phone **376-0895**

No. Shipping Units	DOT PROPER SHIPPING NAME	HAZARD CLASS	Haz Mat. ID No.	EPA Haz Waste No.	WEIGHT	LABELS REQUIRED (or Exemption No.)
3	Asbestos	ORN-C		U013	2750 LB	YES
	LUGGERS				Per Lugger	

## PLACARDS REQUIRED

NOTE - Where the rate is dependent on value, shippers are required to state specifically in writing the agreed or declared value of the property. The agreed or declared value of the property is hereby specifically stated by the shipper to be not exceeding \$ \_\_\_\_\_ Per \_\_\_\_\_

Subject to Section 7 of the conditions, if the shipment is to be delivered to the consignee without receipt, the carrier shall not make delivery of the shipment without payment of freight and all other lawful charges.

FREIGHT CHARGES  
PREPAID ☐ COLLECT ☐

RECEIVED, subject to the classifications and tariffs in effect on the date of the issue of this Bill of Lading, the property described above in apparent good order, except as noted (contents are condition of contents of packages unknown), marked, cosigned, and destined as indicated above which said carrier (the word carrier being understood throughout this contract as meaning any person or corporation in possession of the property under the contract) agrees to carry to its usual place of delivery as said destination, if on its route, otherwise to deliver to another carrier on the route to said destination. It is mutually agreed as to each carrier of all or any of, said property over all or any portion of said route to destination and as to each party at any time interested in all or any said property, that every service to be performed hereunder shall be subject to all the bill of lading terms and conditions in the governing classification on the date of shipment. Shipper hereby certifies that he is familiar with all the bill of lading terms and conditions in the governing classification and the said terms and conditions are hereby agreed to by the shipper and accepted for himself and his assigns.

ALTERNATE DESTINATION (EMERGENCY ONLY)	EMERGENCY RESPONSE INFORMATION
T/S/D FACILITY _____ E.P.A. ID Code No. _____ Address _____ Destination _____	CONTACT Name _____ Phone _____ National Response Center 1-800-424-8802 in D. C. 426-2675

## CERTIFICATION

This is to certify that the above named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and the E.P.A.

Generator Signature **Ronal Nield** Date **9-23-85**

TRANSPORTER #1 **Timothy W. Tolbert** E.P.A. ID No. \_\_\_\_\_  
Address **1111 11th St. Richland, WA 99352**  
City **Richland** State **WA** Zip **99352** Phone **62-8760**

Transporter No. 1 Signature **Timothy W. Tolbert** Date **9-24-85**

TRANSPORTER #2 \_\_\_\_\_ E.P.A. ID No. \_\_\_\_\_  
Address \_\_\_\_\_  
City \_\_\_\_\_ State \_\_\_\_\_ Zip \_\_\_\_\_ Phone \_\_\_\_\_

Transporter No. 2 Signature \_\_\_\_\_ Date \_\_\_\_\_

## TREATMENT/STORAGE/DISPOSAL FACILITY

T/S/D FACILITY \_\_\_\_\_ This is to certify acceptance of the hazardous waste for treatment, storage, or disposal.  
Signature **Al J. El** Date **9-24-85**

TRANSPORTER #2 COPY

000340

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: R. L. Moxin R. L. Moxin

Phone Number: 373-1721

Contractor Contracted By: RHO

Location: 100B, 1142BLM Estimated Volume (ft<sup>3</sup>): 260

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: J. A. Jones Const. Services Co.

Date: 9/18/85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: Paul J. ...

Date: 9/18/85

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: R. L. Morin R.L. MOXIN

Phone Number: 373-1721

Contractor Contracted By: RHO

Location: 100B/182 BLDG Estimated Volume (ft<sup>3</sup>): 350

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: J.A. JONES CONST. SERVICES CO

Date: 7-19-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: M. A. Chubb

Date: 9-19-85

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name:

M. L. M<sup>c</sup>Collom

Phone Number:

376-6706

Contractor Contracted By:

Location:

1167/1100 AREA

Estimated Volume (ft<sup>3</sup>):

50

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name:

M. L. M<sup>c</sup>Collom

Date:

8-26-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator:

M. J. Stahl

Date:

9-16-85

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
  2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
  3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided. See #5
  4. An accurate estimate of the asbestos volume must be provided along with the following information:
  5. Due to the weight of the safes and the condition of the asbestos within, the safes do not require to be double wrapped. Openings are to be taped.
- Generator's Name: Paul Fisher 2752 E/D-103

Approved by J. H. Romero

Phone Number: 373-3694

Contractor Contracted By: \_\_\_\_\_

Location: 200 Areas Estimated Volume (ft<sup>3</sup>): 3670

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: PAUL S FISHER

Date: AUG 22, 1985

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D E Phelps

Date: 9-13-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: Jerry M. Bishop

Phone Number: 376-3518

Contractor Contracted By: UNC

Location: 313/300 Area Estimated Volume (ft<sup>3</sup>): 270

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Jerry M. Bishop

Date: 9/12/85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: A. E. [Signature]

Date: 9-11-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: White CTubes

Phone Number: 273-1731

Contractor Contracted By: J.A. Jones, E.H.O.

Location: 2723-U Estimated Volume (ft<sup>3</sup>): 19200 FT

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: White CTubes

Date: 9-11-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D E Phelps

Date: 9-11-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: See Prichard/JAGGED CONSTRUCTION SERVICES COMPANY

Phone Number: 375-0808

Contractor Contracted By: J. A. JONES CONSTRUCTION SERVICES COMPANY

Location: Woneyard 300 Area Estimated Volume (ft<sup>3</sup>): 304

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Ronald Nield *Ronald Nield*

Date: 3-26-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D E Phelps

Date: 8-29-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: Jerry M. Rishard

Phone Number: 376-3518

Contractor Contracted By: UNK

Location: 313 Estimated Volume (ft<sup>3</sup>): 270

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Dan N. Buring

Date: 8-26-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D. E. F. [Signature]

Date: 8-26 1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: John J. Campbell

Phone Number: 2-2-4530

Contractor Contracted By: UIC

Location: 100A Estimated Volume (ft<sup>3</sup>): 100 F13

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: J. H. Jones Construction Services Co.

Date: 8/12/85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: DE [Signature]

Date: 8-12-1985

# ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any air-borne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: Emory Stubblefield Co

Phone Number: 509 525-5572

Contractor Contracted By: Rockwell Cross

Location: 184 B Estimated Volume (ft<sup>3</sup>): 402 cu-ft  
13 bags

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Emory Stubblefield Co. By: *Quaker Swanson*

Date: 8/8/85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: *D E Phelps*

Date: 8-8-85

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: S.E. Jones

Phone Number: 373-2456

Contractor Contracted By: Rockwell

Location: 221 B Estimated Volume (ft<sup>3</sup>): 250

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: S.E. Jones

Date: 07-29-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D.E. Phelps

Date: 7-29-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: George Constantine

Phone Number: 373-1621

Contractor Contracted By: UNC

Location: 100W Estimated Volume (ft<sup>3</sup>): 256 Cu. Ft

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: J. A. Jones Const. Co.

Date: 1-11-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D E Phelps

Date: 7-19 1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: Robert F. Gretzinger

Phone Number: 373-3806

Contractor Contracted By: Rockwell Utilities

Location: 300 Area Estimated Volume (ft<sup>3</sup>): 18

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Robert F. Gretzinger

Date: 7/1/85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: 10 E T. R. R. R.

Date: 7-2-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: Qian Hanford

Phone Number: 3716-3036

Contractor Contracted By: Rockwell Hanford

Location: 171 Bldg 1100 Area

Estimated Volume (ft<sup>3</sup>): 20F

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Qian Hanford

Date: 6-25-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D. E. Phelps

Date: 6-26-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: Gh Campbell

Phone Number: 3-1121

Contractor Contracted By: RHO

Location: 284 W Estimated Volume (ft<sup>3</sup>): 100 cu ft

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: x H. L. Campbell

Date: 6/18/85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D E Felt

Date: 6 20 1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: BH CLARK

Phone Number: 3-2355

Contractor Contracted By: RHC

Location: 2101 m Estimated Volume (ft<sup>3</sup>): 100 cu ft

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: B. Clark

Date: 6/18/85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D E Phelps

Date: 6-20-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: Dee Prichard/J. A. Jones Construction Services Company

Phone Number: 376-0896

Contractor Contracted By: J. A. Jones Construction Services Co.

Location: Loneyard 300 Area Estimated Volume (ft<sup>3</sup>): 304

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Victor Tarr *Victor Tarr*

Date: 5-23-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D E Phelps

Date: 5-30-1985

*SUBMIT 800593  
J. A. Jones  
5-30-85*

# HAZARDOUS WASTE MANIFEST

**THIS SHIPPING ORDER**

must be legibly filled in, in ink, in Indefinite Pencil, or in Carbon, and retained by the Agent.

MANIFEST DOCUMENT NUMBER

85-002

TO: T/S/D FACILITY E.P.A. ID Code No. Address Destination Phone	CENTRAL LANDFILL      	FROM: Generator E.P.A. ID Code No. Address Origin Phone	J. A. Jones Construction Services Co. WA7890008967 801 1st St. Richland, WA 99352 300 Area 376-0895
--	--	--	---

No Shipping Units	D.O.T. PROPER SHIPPING NAME	HAZARD CLASS	Haz Mat ID No	EPA Haz Waste No	WEIGHT	LABELS REQUIRED (or Exemption No.)
2	Asbestos	ORM-C		U013	2750 LB	YES
	Luggers				PER LUGGER	

## PLACARDS REQUIRED

NOTE - Where the rate is dependent on value, shippers are required to state specifically in writing the agreed or declared value of the property. The agreed or declared value of the property is hereby specifically stated by the shipper to be not exceeding \$ \_\_\_\_\_ Per \_\_\_\_\_

Subject to Section 7 of the conditions, if this shipment is to be delivered to the consignee without payment as the consignor, the consignor shall sign the following statement:  
The carrier shall not make delivery of this shipment without payment of freight and all other lawful charges.  
  
(Signature of Consignor)

## FREIGHT CHARGES

PREPAID ☐ COLLECT ☐

RECEIVED, subject to the classifications and tariffs in effect on the date of the issue of this Bill of Lading, the property described above in apparent good order, except as noted (contents and condition of containers of packages, unknown, marked, consigned, and destined as indicated above which said carrier (the word carrier being understood throughout this contract as meaning any person or corporation in possession of the property under the contract) agrees to carry to its usual place of delivery at said destination, if on its route, otherwise to deliver to another carrier on the route to said destination. It is mutually agreed as to each carrier of all or any of, said property over all or any portion of said route to destination and as to each party at any time interested in all or any said property, that every service to be performed hereunder shall be subject to all the bill of lading terms and conditions in the governing classification on the date of shipment. Shipper hereby certifies that he is familiar with all the bill of lading terms and conditions in the governing classification and the said terms and conditions are hereby agreed to by the shipper and accepted for himself and his assigns.

<b>ALTERNATE DESTINATION (EMERGENCY ONLY)</b> T/S/D FACILITY _____ E.P.A. ID Code No. _____ Address _____ Destination _____	<b>EMERGENCY RESPONSE INFORMATION</b> CONTACT Name _____ Phone _____ National Response Center 1-800-424-8802 in D. C. 426-2675
---	--

## CERTIFICATION

This is to certify that the above named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and the E.P.A.

Generator Signature Ronald Nield Date 5-23-85

TRANSPORTER #1 \_\_\_\_\_ E.P.A. ID No. \_\_\_\_\_  
 Address \_\_\_\_\_  
 City \_\_\_\_\_ State \_\_\_\_\_ Zip \_\_\_\_\_ Phone \_\_\_\_\_

This is to certify acceptance of the hazardous waste shipment.

Transporter No. 1 Signature \_\_\_\_\_ Date \_\_\_\_\_

TRANSPORTER #2 \_\_\_\_\_ E.P.A. ID No. \_\_\_\_\_  
 Address \_\_\_\_\_  
 City \_\_\_\_\_ State \_\_\_\_\_ Zip \_\_\_\_\_ Phone \_\_\_\_\_

This is to certify acceptance of the hazardous waste shipment.

Transporter No. 2 Signature K. L. Steensma Date 5-30-85

## TREATMENT/STORAGE/DISPOSAL FACILITY

T/S/D FACILITY \_\_\_\_\_ This is to certify acceptance of the hazardous waste for treatment, storage, or disposal.  
 Signature D. E. Phelps Date 5-30-1985

TRANSPORTER #1 COPY

000358

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: DELBERT W NELSON

Phone Number: 373-1390

Contractor Contracted By: DEL W. NELSON

Location: 100 N Estimated Volume (ft<sup>3</sup>): 275

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Delbert W Nelson

Date: 5-29-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D E Phelps

Date: 5-29-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: Adams Dismantling

Phone Number: 932-4261

Contractor Contracted By: Adams Dismantling 20-cu-ft

Location: 183 B Estimated Volume (ft<sup>3</sup>): \_\_\_\_\_

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Jerry A. Cribben

Date: May 21 85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D E Phelps

Date: 5-21-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: PUREX 207A/200E R.L. NELSON

Phone Number: 373-2323

Contractor Contracted By: RHO

Location: 207A/200E Estimated Volume (ft<sup>3</sup>): 135 CF  
5405

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Ronald T. Nelson

Date: 5/20/85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D E Phelps

Date: 5-20-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name:

S E Vosevich

Phone Number:

33873

Contractor Contracted By:

UNC

Location:

100N

Estimated Volume (ft<sup>3</sup>):

45 C FT

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name:

Andrea E. Vosevich

Date:

The above requirements have been met and the estimated volume appears correct.

Landfill Operator:

D E Phelps

Date:

5-15-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: Hodgson

Phone Number: 323 4601

Contractor Contracted By: UAC

Location: 115-D Estimated Volume (ft<sup>3</sup>): 315

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: JE Hoxie

Date: 5-8-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: Q E Ripe

Date: 5-8-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: Hodgson

Phone Number: 373 4601

Contractor Contracted By: UNC

Location: 115-D Estimated Volume (ft<sup>3</sup>): 8 315

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: J. H. Hays

Date: 5/7/84

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D. E. Phelps

Date: 5-7-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: J E Hodgson

Phone Number: 3734601

Contractor Contracted By: UNOC

Location: 11T-D - 11S-D/DK Estimated Volume (ft<sup>3</sup>): 5-2

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: J E Hodgson

Date: 4/22/85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: R R Harrison

Date: 4-22-85

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name:

J.E. Hodgson

Phone Number:

373 4601

Contractor Contracted By:

UAC

Location:

100-D-115-D/DR

Estimated Volume (ft<sup>3</sup>):

512

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name:

J.E. Hodgson

Date:

8-19-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator:

D.E. Phelps

Date:

4-19-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be double plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: Lester V. C. [Signature]

Phone Number: 372-2457

Contractor Contracted By: RHO

Location: 224-V/200 WEST Estimated Volume (ft<sup>3</sup>): 270

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: [Signature]

Date: 4/8/85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: [Signature]

Date: 4 12 1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: Jerry M. Bishop

Phone Number: 376-3518

Contractor Contracted By: UNIC

Location: 313 Estimated Volume (ft<sup>3</sup>): 270

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Jerry M. Bishop

Date: 3-29-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D E T Roper

Date: 3-28-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: MICHAEL E. THURMAN

Phone Number: 3-3544

Contractor Contracted By: UWC

Location: 105-D Estimated Volume (ft<sup>3</sup>): 180

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Michael E. Thurman

Date: 3/25/85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D E Fisher

Date: 3-25-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: MICHAEL E. THURMAN

Phone Number: 3-3544

Contractor Contracted By: UNC

Location: 105-D Estimated Volume (ft<sup>3</sup>): 197

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Michael E. Thurman

Date: 3/22/85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D E Phelps

Date: 3-22-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: CARL C. SCHOCK

Phone Number: 373-2188

Contractor Contracted By: LLNC

Location: 100 N AREA Estimated Volume (ft<sup>3</sup>): 275

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: CARL C. SCHOCK

Date: 3-21-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: The Requirements HAS NOT BEEN MET  
PAPER WORK NOT RIGHT

Date: 3-21-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: MICHAEL E THURMAN

Phone Number: 3-3544

Contractor Contracted By: UNCC

Location: 105-0 Estimated Volume (ft<sup>3</sup>): 180

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Michael E. Thurman

Date: 3/21/85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: 19 E Phelps

Date: 3-21-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: MICHAEL E. THURMAN

Phone Number: 3-3544

Contractor Contracted By: UNC

Location: 115-B/C Estimated Volume (ft<sup>3</sup>): 175 cu FT

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Michael E. Thurman

Date: 3/14/85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D E Phelps

Date: 3-15-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: MICHAEL E. THURMAN

Phone Number: 3-3544

Contractor Contracted By: UNC

Location: 115-B/C Gas Wing Estimated Volume (ft<sup>3</sup>): 180 cu ft

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Michael E. Thurman

Date: 3/12/85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D E P. [Signature]

Date: 3-12-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: GL Campbell

Phone Number: 3-1121

Contractor Contracted By: RHO

Location: 284 W Estimated Volume (ft<sup>3</sup>): 100 cu ft

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: x ~~GL Campbell~~

Date: 3/7/85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: DE Phelps

Date: 3-12-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: B.H. CLARK

Phone Number: 3-2355

Contractor Contracted By: RHO

Location: 2101 M Estimated Volume (ft<sup>3</sup>): 100 cu ft

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: B.H. Clark

Date: 3/7/85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D E T P

Date: 3-11-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: Dwight Hand

Phone Number: 373-3666

Contractor Contracted By: UAC

Location: 107C Retention Basin Estimated Volume (ft<sup>3</sup>): 252 Cubic Ft.

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Dwight Hand

Date: 3/7/85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: Q E Phelps

Date: 3-7-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: Twight W. HAND

Phone Number: 373-3666

Contractor Contracted By: UAC

Location: 107 Retention Basin Estimated Volume (ft<sup>3</sup>): 176 cu. ft.

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Twight Hand

Date: 3/7/85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D E Phelps

Date: 3-7-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: FOKER

Phone Number: 973-2323

Contractor Contracted By: ROCKWELL HANFORD OPERATIONS

Location: 202A/200E Estimated Volume (ft<sup>3</sup>): 6

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: R. J. L. S.

Date: 3/1/85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D E T. Lopez

Date: 3-4-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name:

J. E. Hodgson UNCL

Phone Number:

373-3368

Contractor Contracted By:

UNCL

Location:

115-B

Estimated Volume (ft<sup>3</sup>):

252 Cu Ft

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name:

J. E. Hodgson

Date:

2-22-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator:

D. E. Phelps

Date:

2-22-1985

A:

Counted

EST

The Industrial Hygiene & Safety [  
of asbestos management at Hanf  
requirements for asbestos at the Central Landfill Asbestos Trench:

II Hanford Operations has control  
established the following disposal

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: S. E. Jones

Phone Number: 373-2456

Contractor Contracted By: Rockwell

Location: 221B Estimated Volume (ft<sup>3</sup>): 250

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: SE Jones

Date: 01-18-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D E Phelps

Date: 1 - 21 1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: Dee Prichard/J. A. Jones Construction Services Company

Phone Number: 376-0895

Contractor Contracted By: J. A. Jones Construction Services Company

Location: Boneyard 300 Area Estimated Volume (ft<sup>3</sup>): ~~XXX~~ 304

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Ronald Nield *Ronald Nield*

Date: 1-16-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: *C. E. Prichard*

Date: 1-17-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: CARL C. SCHOCK

Phone Number: 3-2249

Contractor Contracted By: UNC

Location: 100N Estimated Volume (ft<sup>3</sup>): 275

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Carl Schock

Date: 1-4-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D E T. Phelps

Date: 1-3-1985

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: Jerry M. Bishop

Phone Number: 376-3518

Contractor Contracted By: UNC / Rockwell

Location: 313 Dock Estimated Volume (ft<sup>3</sup>): 216

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Jerry M. Bishop

Date: 1-11-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D. E. Phillips

Date: 1-11-1985

# HAZARDOUS WASTE MANIFEST

## THIS SHIPPING ORDER

must be legibly filled in, in ink, in Indelible Pencil, or in Carbon, and retained by the Agent.

MANIFEST DOCUMENT NUMBER

85-001

TO: T/S/D FACILITY CENTRAL LANDFILL	FROM: Generator J. A. Jones Construction Service Co.
E.P.A. ID Code No.	E.P.A. ID Code No. WA7390008967
Address	Address 801 First St. Richland, WA 99352
Destination	Origin 300 Area
Phone	Phone 376-0395

No Shipping Units	D.O.T. PROPER SHIPPING NAME	HAZARD CLASS	Haz Mat ID No.	EPA Haz Waste No.	WEIGHT	LABELS REQUIRED (or Exemption No.)
2	Asbestos	OR1-C		U013	2750 LB	YES
	Luggers				per lugger	

### PLACARDS REQUIRED

NOTE - Where the rate is dependent on value, shippers are required to state specifically in writing the agreed or declared value of the property. The agreed or declared value of the property is hereby specifically stated by the shipper to be not exceeding \$ \_\_\_\_\_ Per \_\_\_\_\_

Subject to Section 7 of the conditions, if this shipment is to be delivered to the consignee without recourse to the carrier, the carrier shall sign the following statement:  
The carrier shall not make delivery of this shipment without payment of freight and all other lawful charges.

FREIGHT CHARGES  
PREPAID ☐ COLLECT ☐

(Signature of Carrier)

RECEIVED, subject to the classifications and tariffs in effect on the date of the issue of this Bill of Lading, the property described above in apparent good order, except as noted (contents and condition of contents of packages unknown), marked, consigned, and destined as indicated above which said carrier (the word carrier being understood throughout this contract as meaning any person or corporation in possession of the property under the contract) agrees to carry to its usual place of delivery at said destination, if on its route, otherwise to deliver to another carrier on the route to said destination. It is mutually agreed as to each carrier of all or any of, said property over all or any portion of said route to destination and as to each party at any time interested in all or any said property, that every service to be performed hereunder shall be subject to all the bill of lading terms and conditions in the governing classification on the date of shipment.  
Shipper hereby certifies that he is familiar with all the bill of lading terms and conditions in the governing classification and the said terms and conditions are hereby agreed to by the shipper and accepted for himself and his assigns.

ALTERNATE DESTINATION (EMERGENCY ONLY)	EMERGENCY RESPONSE INFORMATION
T/S/D FACILITY _____	CONTACT Name _____
E.P.A. ID Code No. _____	Phone _____
Address _____	National Response Center 1-800-424-8802
Destination _____	in D. C. 426-2675

### CERTIFICATION

This is to certify that the above named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation and the E.P.A.

Generator Signature Ronald Nield Date 1-16-85

TRANSPORTER #1 1171 E.P.A. ID No. \_\_\_\_\_  
Address 1171 State WA Zip 99352 Phone 376-0395  
City Richland

This is to certify acceptance of the hazardous waste shipment.

Transporter No. 1 Signature 1171 Date 1-17-85

TRANSPORTER #2 \_\_\_\_\_ E.P.A. ID No. \_\_\_\_\_  
Address \_\_\_\_\_  
City \_\_\_\_\_ State \_\_\_\_\_ Zip \_\_\_\_\_ Phone \_\_\_\_\_

This is to certify acceptance of the hazardous waste shipment.

Transporter No. 2 Signature \_\_\_\_\_ Date \_\_\_\_\_

### TREATMENT/STORAGE/DISPOSAL FACILITY

This is to certify acceptance of the hazardous waste for treatment, storage, or disposal.

T/S/D FACILITY Signature O E P Date 1-17-1985

TRANSPORTER #1 COPY

000385

## ASBESTOS DISPOSAL REQUEST

The Industrial Hygiene & Safety Department (IH&S) of Rockwell Hanford Operations has control of asbestos management at Hanford. Accordingly, IH&S has established the following disposal requirements for asbestos at the Central Landfill Asbestos Trench:

1. A radiation release must be obtained for any asbestos emanating from a Radiation Zone.
2. All asbestos material packaged for disposal must be thoroughly wetted to eliminate any airborne asbestos particles during transportation, handling, or burial.
3. All asbestos material must be doubled plastic bagged or wrapped (6 mil or equivalent) to eliminate any airborne asbestos particles. A seal to preclude environmental or personnel exposure should be provided.
4. An accurate estimate of the asbestos volume must be provided along with the following information:

Generator's Name: CARL C. SCHOCK

Phone Number: 3-2249

Contractor Contracted By: UNCC

Location: 100N Estimated Volume (ft<sup>3</sup>): 275

I have read and accept responsibility for the above outlined requirements for disposal of asbestos material.

Generator Name: Carl Schock

Date: 1-4-85

The above requirements have been met and the estimated volume appears correct.

Landfill Operator: D E T. Phelps

Date: 1-3-1985